



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH EDITION TDI
Colour	Red
Year of manufacture	2013
Top speed	105 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.000 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	B



**MOT history**

MOT expiry date	2022-03-18
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	7
Total items failed	6

MOT #6	2021-03-19 14:01
MOT test number	870408449873
Result	✓ Passed
Next expiry date	2022-03-18
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #5	2020-06-17 11:30
MOT test number	963026630894
Result	✗ Failed
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Headlamp aim too low (4.1.2 (a))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #4** 2019-06-27 16:18**MOT test number** 122824705708**Result** ✓ Passed**Advice** Under tray fitted obscuring view of engine components**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #3** 2019-06-26 17:16**MOT test number** 665930862719**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Under tray fitted obscuring view of engine components**Fail** Rear Service brake excessively binding (1.2.1 (f))**MOT #2** 2018-06-25 14:57**MOT test number** 600731781038**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2017-03-15 16:45**MOT test number** 233656237087**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BJ63KLU
Plate since	2019-09-29
Current registration	 BJ63KLU
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2013-10-29
Last registration	2021-03-19
Complete history	See info



Registration #1	2013-10-29	24 mi
Registration #2	2017-03-15	14.390 mi
Registration #3	2018-06-25	22.193 mi
Registration #4	2019-06-26	28.940 mi
Registration #5	2020-03-20	35.377 mi
Registration #6	2020-03-20	35.377 mi
Registration #7	2021-03-19	35.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	CFWA366345