





report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	Red
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/10



EO14HDU report date: 2024-03-28

MOT history

MOT expiry date	2022-04-12
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	10
Total items failed	6

MOT #8	2021-04-12 11:23
MOT test number	803356264713
Result	✓ Passed
Next expiry date	2022-04-12
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.3	L.14 (a) (ii))

MOT #7	2021-04-12 11:23
MOT test number	628672628056
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification Offside Front Seat belt anchorage loose (7.1.1 (b))	

MOT #6	2020-03-25 11:11
MOT test number	942071114382
Result	✓ Passed
Advice Rear silencer corroding.	

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT test number

Result

Advice Rear silencer corroding.

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT test number

Result

Advice (a) (i))

Advice (a) (i))

Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (

MOT #3	2018-04-13 12:36
MOT test number	834880057539
Result	✓ Passed

MOT #2		2018-04-13 08:05
MOT tes	t number	215704609327
Result		X Failed
Fail	Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail	Nearside Stop lamp not working (1.2.1b)	

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT #1		2017-04-11 11:51
MOT test	number	883870853011
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners die Check it in the premium report and see all owner registrations. Download the full report is	

2000000	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK ZIN
Plate since	
Current registration	UK SIP
Plate since	
	More info >

CarCheck.co.uk page 7/10



EO14HDU report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-03-31
Last registration	2021-04-12
Complete history	See info



Registration #1	2014-03-31	13 mi
Registration #2	2017-04-11	23.768 mi
Registration #3	2018-04-13	35.082 mi
Registration #4	2018-04-13	35.082 mi
Registration #5	2019-04-02	37.687 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/3

Number of axles2Engine number0798077