



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2024-12-20
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	30
Total items failed	17

MOT #18	2023-12-11 07:09
MOT test number	475946877401
Result	✓ Passed
Next expiry date	2024-12-20

MOT #17	2022-12-20 10:30
MOT test number	648223065633
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-12-17 11:50
MOT test number	859505481492
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #15** 2021-12-16 11:12**MOT test number** 454522002899**Result** ✓ Passed**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #14** 2020-12-04 12:32**MOT test number** 939920596471**Result** ✓ Passed**MOT #13** 2019-12-12 14:53**MOT test number** 372587943769**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #12** 2019-12-12 11:58**MOT test number** 257555185690**Result** ✗ Failed**Fail** Offside Front Obligatory mirror insecure (3.3 (b) (ii))**Advice** Nearside Rear Nail in tyre**MOT #11** 2018-12-21 12:28**MOT test number** 989137815735**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2018-12-20 11:39

MOT test number

878197013860

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9

2018-11-02 10:02

MOT test number

733842202496

Result**✗ Failed**

- Advice** Nearside Rear alloy wheel buckled
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Central Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Rear Exhaust system insecure (6.1.2 (a))
- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Front Exhaust system insecure (6.1.2 (a))
- Fail** Front Service brake excessively fluctuating (1.2.1 (e))

**MOT #8**

2018-09-18 09:11

MOT test number

656244239944

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge No tread on edges, worn to 2mm in middle 3/4 (5.2.3 (e))

Advice Offside Play in steering rack inner joint(s)

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front discs worn and slightly corroded (1.1.14 (a) (ii))

MOT #7

2018-09-17 08:34

MOT test number

639354500672

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge No tread on edges, worn to 2mm in middle 3/4 (5.2.3 (e))

Fail Nearside Front Suspension arm pin or bush excessively worn Lower wishbone rear bush worn and split, excessive movement on lock (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front discs worn and slightly corroded (1.1.14 (a) (ii))

Advice Offside Play in steering rack inner joint(s)

Fail Offside Front Suspension arm pin or bush excessively worn Lower wishbone rear bush worn and splitting, excessive movement on lock (5.3.4 (a) (i))

MOT #6

2017-06-27 10:21

MOT test number

204835621409

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened Light grooving on both front brake discs (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit on inner edge of tread, middle 3/4 ok (4.1.E.1)

MOT #5

2016-06-03 11:34

MOT test number

314836593163

Result

✓ Passed

Advice Engine covers fitted obscuring some components in the engine bay and underside

**MOT #4** 2015-06-02 08:59**MOT test number** 247333255152**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Osf tyre wearing on edges**MOT #3** 2014-05-26 09:12**MOT test number** 456026344147**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2013-06-04 16:40**MOT test number** 399075453135**Result** ✓ Passed**MOT #1** 2013-05-29 17:18**MOT test number** 477609043112**Result** ✗ Failed**Fail** Rear registration plate deteriorated (6.3.1d)**Fail** Front registration plate deteriorated (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EJ10VFK
Plate since	2019-03-28
Current registration	EJ10VFK
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-08
Last registration	2023-12-11
Complete history	See info



Registration #1	2010-06-08	17 mi
Registration #2	2013-05-29	23.695 mi
Registration #3	2013-06-04	23.695 mi
Registration #4	2014-05-26	26.576 mi
Registration #5	2015-06-02	29.935 mi
Registration #6	2016-06-03	33.438 mi
Registration #7	2017-06-27	37.206 mi
Registration #8	2018-09-17	40.877 mi
Registration #9	2018-09-18	40.877 mi
Registration #10	2018-11-02	41.473 mi
Registration #11	2019-05-29	41.473 mi
Registration #12	2019-05-29	41.473 mi
Registration #13	2019-05-29	41.473 mi
Registration #14	2019-05-29	41.473 mi
Registration #15	2019-05-29	41.473 mi
Registration #16	2019-05-29	41.473 mi
Registration #17	2019-05-29	41.473 mi
Registration #18	2019-05-29	41.473 mi
Registration #19	2019-05-29	41.473 mi
Registration #20	2019-05-29	41.473 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1839 mm
Height	1497 mm
Length	4337 mm
Kerb weight	1239 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Engine number	AJ72274