



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GBT
Colour	Black
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-21
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-21
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	36
Total items failed	8

MOT #15	2023-11-22 13:34
MOT test number	792418282991
Result	✓ Passed
Next expiry date	2024-11-21
Advice	Rear exhaust back box outer skin corroded

MOT #14	2023-09-15 08:14
MOT test number	429315384898
Result	✓ Passed
Advice	Rear silencer outer skin corroded

MOT #13	2022-09-22 16:34
MOT test number	592167050186
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Exhaust rear silencer corroded

**MOT #12** 2022-09-14 11:29**MOT test number** 516617707103**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Rear Exhaust rear silencer corroded**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-09-14 10:10**MOT test number** 287794400777**Result** ✓ Passed**MOT #10** 2021-09-13 16:04**MOT test number** 751707358009**Result** ✗ Failed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Nearside Rear Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #9** 2020-07-21 13:34**MOT test number** 426841171798**Result** ✓ Passed

- Advice** Rear exhaust box rusty and slight leak
- Advice** Nearside and offside rear shock absorbers slight leak
- Advice** Offside tyre inner edge worn

MOT #8 2020-07-21 09:10**MOT test number** 110539426706**Result** ✗ Failed

- Advice** Front brake discs and pads worn
- Advice** Rear exhaust box rusty and slight leak
- Advice** Offside tyre inner edge worn
- Advice** Nearside and offside rear shock absorbers slight leak
- Advice** Rear wiper blade
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nail in nearside rear tyre

MOT #7 2019-07-23 11:59**MOT test number** 636165016097**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
- Advice** Rear Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))

**MOT #6** 2019-07-23 11:59**MOT test number** 977501515512**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))**Advice** Rear Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))**MOT #5** 2018-08-02 10:11**MOT test number** 855306286098**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #4** 2017-08-03 10:27**MOT test number** 731468044388**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2016-08-09 14:30**MOT test number** 287241982843**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #2	2016-08-09 14:30
MOT test number	846231448903
Result	✗ Failed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #1	2015-08-14 14:53
MOT test number	830465673747
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
21 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	WU12RDO
Plate since	2019-03-29
Current registration	WU12RDO
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-04-27
Last registration	2023-11-22
Complete history	See info



Registration #1	2012-04-27	24 mi
Registration #2	2015-08-14	15.580 mi
Registration #3	2016-08-09	20.332 mi
Registration #4	2016-08-09	20.332 mi
Registration #5	2017-08-03	24.564 mi
Registration #6	2018-08-02	28.813 mi
Registration #7	2019-07-23	33.035 mi
Registration #8	2019-07-23	33.035 mi
Registration #9	2020-07-21	37.542 mi
Registration #10	2020-07-21	37.542 mi
Registration #11	2020-07-21	37.542 mi
Registration #12	2020-07-21	37.542 mi
Registration #13	2020-07-21	37.542 mi
Registration #14	2020-07-21	37.542 mi
Registration #15	2020-07-21	37.542 mi
Registration #16	2020-07-21	37.542 mi
Registration #17	2020-07-21	37.542 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number	0091898
---------------	---------