






report date: 2024-03-29

### General information

Make	RENAULT
Model	MASTER LM35 BUSINESS ENERGY DCI
Colour	White
Year of manufacture	2017
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	145 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	2.298 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	39.2 mpg
CO2 emission	186 g/km
CO2 label	J



CarCheck.co.uk page 1/11



**AV67BNU** 

report date: 2024-03-29

## Internet history

### Entry 1

Date 2022-04-08

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



**AV67BNU** 

report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-22
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	7
Total items failed	4

MOT #6		2024-02-05 16:35
MOT test	number	498306369471
Result		✓ Passed
Next expi	ry date	2025-02-22
Advice	Offside Rear Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5	2023-02-23 17:01
MOT test number	977310295063
Result	✓ Passed

MOT #4	2023-02-23 17:01
MOT test number	784490156198
Result	<b>X</b> Failed
Pass with rectification the windscreen (3.5 (a))	Nearside Windscreen washer jets misaligned and not providing sufficient fluid to

**Pass with rectification** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

CarCheck.co.uk page 3/11



**AV67BNU** 

report date: 2024-03-29

2021-12-03 14:41 **MOT** #3 800648014795 **MOT** test number Result ✓ Passed **Advice** Front Service brake binding but not excessively Both (1.2.1 (f)) Advice Offside Rear Nail in tyre Advice Fluid leak, but not excessive Adblue tank minor leak (8.4.1 (a) (i)) Advice Rear Service brake binding but not excessively Both (1.2.1 (f)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))

MOT #2 2020-12-03 12:26

MOT test number 168769940707

Result ✓ Passed

 MOT #1
 2020-12-03 12:26

 MOT test number
 384915866842

 Result
 X Failed

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 4/11



#### Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	22 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
********	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-20
Last registration	2024-02-05
Complete history	See info



Registration #1	2017-12-20	25 mi
Registration #2	2020-12-03	56.334 mi
Registration #3	2020-12-03	56.334 mi
Registration #4	2021-12-03	78.863 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Dimensi	ODC A.	M	nt.

Width	2470 mm
Height	2496 mm
Length	6198 mm
Kerb weight	2029 kg
Max. allowed weight	3500 kg

## Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	3
Engine number	C024052

CarCheck.co.uk page 11/11