





report date: 2024-03-29

## General information

Make	PEUGEOT	
Model	PARTNER BLUE HDI PROFESSIONAL L1	
Colour	White	
Year of manufacture	2018	
Top speed	101 mph	
Gearbox	5 speed Manual	

# Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history

### Entry 1

Date 2021-06-26

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



**MOT** history

MOT expiry date	2024-10-05
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	22
Total items failed	4


MOT #7		2023-10-06 11:13
MOT test	number	776067844793
Result		✓ Passed
Next exp	ry date	2024-10-05
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deter	riorated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (b) (i))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/12



EJ18HRW

report date: 2024-03-29



MOT #5		2022-07-07 08:41
MOT test number		295375145137
Result		<b>✓</b> Passed
Advice Nearside Front nail	in tyre	
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Advice Offside Rear has sl	ight flat spot	

MOT #4	2022-07-07 08:41	
MOT test number	894668778324	
Result	<b>X</b> Failed	
Advice Nearside Front nail in tyre		
Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))		
Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))		
Advice Offside Rear has slight flat spot		

CarCheck.co.uk page 4/12



MOT #3 2021-07-08 12:39

**MOT test number** 967182416251

MOT #2 2021-04-22 09:50

MOT test number 256422501111

Result Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #1 2021-04-22 09:50

**MOT test number** 880155668928

**Result** X Failed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Pass with rectification Nearside Rear Registration plate lamp likely to become detached (4.7.1 (c) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



**EJ18HRW** 

report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	5 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
**********	
***************************************	
************	
********	
***************************************	
************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK SIPE
Plate since	
Current registration	NIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



EJ18HRW

report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-30
Last registration	2023-10-06
Complete history	See info



B	2010 04 20	24
Registration #1	2018-04-30	14 mi
Registration #2	2021-04-22	73.783 mi
Registration #3	2021-04-22	73.783 mi
Registration #4		11.777 es
Registration #5	2021-07-08	74.359 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
S0569	

# Dimensions & weight

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1331 kg
Max. allowed weight	2185 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JBHB0082207

CarCheck.co.uk page 12/12