





report date: 2024-03-28

### General information

Make	MINI
Model	ONE AUTO COOPER
Colour	Black
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

### Entry 2

Date 2022-04-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-03

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

MOT expiry date	2024-06-11
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	22
Total items failed	4

MOT #13		2023-06-12 08:01
MOT test	number	850273085141
Result		✓ Passed
Next expi	ry date	2024-06-11
Advice	Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #12	2022-05-12 08:33
MOT test number	698693387966
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))	

MOT #11	2022-05-10 15:25
MOT test number	977625258461
Result	<b>×</b> Failed
Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Front Exhaust has a minor leak of exhaust gases flexi broken (6.1.2 (a))	
Minor Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))	

CarCheck.co.uk page 3/13



Result

LG62FMU

report date: 2024-03-28

✓ Passed

MOT #10 2021-05-01 09:31 MOT test number 272845137670

**Result** 
✓ Passed

MOT #9 2020-07-23 13:38

**MOT test number** 457195867774

Advice Offside Front Tyre slightly damaged on outer sidewall and getting close to limit. (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides. (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Exhaust has a minor leak of exhaust gases Front flexi. (6.1.2 (a))

**Advice** Rear Inner Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii))

CarCheck.co.uk page 4/13



Result

LG62FMU

report date: 2024-03-28

✓ Passed

**MOT #8** 2020-07-23 13:26 **MOT** test number 223179375739 Result × Failed **Advice** Rear Inner Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii)) **Advice** Offside Front Tyre slightly damaged on outer sidewall and getting close to limit. (5.2.3 (d) (ii)) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail **Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii)) Front Brake disc worn, pitted or scored, but not seriously weakened Both sides. (1.1.14 (a) (ii)) **Advice Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Exhaust has a minor leak of exhaust gases Front flexi. (6.1.2 (a)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2019-05-28 12:33 MOT test number 463275730221

**MOT #6** 2019-04-18 16:06

**MOT test number** 419677235769

**Result** X Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge edges & shredding at tread (5.2.3 (e))

 MOT #5
 2018-04-06 11:16

 MOT test number
 772477207951

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4	2018-04-03 11:54
MOT test number	132595582550
Result	<b>×</b> Failed
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)		
MOT #3	2017-04-06 10:26	
MOT test number	481083628220	
Result	<b>✓</b> Passed	
MOT #2	2016-04-19 10:32	
MOT test number	715351198411	
Result	✓ Passed	
MOT #1	2015-09-16 14:56	
MOT test number	714596898177	
Result	✓ Passed	

CarCheck.co.uk page 6/13



report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	11 June 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



LG62FMU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have?  Check it in the premium report and see all owner registrations. Download the full report here.  More info >  Plate changes  See in this check if this MINI had different number plates.		
Plate changes  See in this check if this MINI had different number plates.		
Plate changes  See in this check if this MINI had different number plates.		
Plate changes  See in this check if this MINI had different number plates.	*********	
Plate changes  See in this check if this MINI had different number plates.		
Plate changes  See in this check if this MINI had different number plates.	************	
Plate changes  See in this check if this MINI had different number plates.		
Plate changes  See in this check if this MINI had different number plates.	HARMAN AND AND AND AND AND AND AND AND AND A	
Plate changes  See in this check if this MINI had different number plates.		
Plate changes  See in this check if this MINI had different number plates.	THE STATE OF THE S	
Plate changes  See in this check if this MINI had different number plates.		
See in this check if this MINI had different number plates.		More info >
See in this check if this MINI had different number plates.		
EXECUTE OF THE PROPERTY OF THE	Plate changes	
₩ UK	See in this check if this MINI had different number plates.	
₩ UK	Number of plates	
Plate since	Current registration	UK NIK
Plate since	Plate since	
More info	Current registration	IIK SINS
More info	Plate since	
Page mile /		More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-26
Last registration	2023-06-12
Complete history	See info



Registration #1	2012-09-26	28 mi
Registration #2	2015-09-16	8.617 mi
Registration #3	2016-04-19	9.773 mi
Registration #4	2017-04-06	11.909 mi
Registration #5	2018-04-03	13.498 mi
Registration #6	2018-04-06	13.540 mi
Registration #7	2019-04-18	15.129 mi
Registration #8	2019-05-28	15.172 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

77,777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1105 kg
Max. allowed weight	1570 kg

## Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles2Engine numberB081J342