



EX60NFT

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg



**MOT history**

MOT #13	2023-01-14 16:01
MOT test number	687794262182
Result	✓ Passed
Next expiry date	2024-02-02

MOT #12	2022-02-01 10:08
MOT test number	305164323957
Result	✓ Passed

MOT #11	2021-02-03 15:00
MOT test number	908228438286
Result	✓ Passed

MOT #10	2019-07-05 14:45
MOT test number	532087338148
Result	✓ Passed

MOT #9	2019-07-05 14:45
MOT test number	508649924867
Result	✗ Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #8	2018-07-06 11:35
MOT test number	897000070047
Result	✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2017-06-14 16:15
MOT test number	668401705610
Result	✓ Passed



MOT #6	2016-06-10 10:50
MOT test number	753457530021
Result	✓ Passed
Advice	Nearside Front TRE locking nut loose

MOT #5	2016-06-07 15:45
MOT test number	184958241099
Result	✗ Failed
Advice	Nearside Front TRE locking nut loose
Fail	Nearside Front Front position lamp(s) not working (1.1.A.3b)
Fail	Front registration plate delaminated (6.3.1d)
Fail	Nearside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

MOT #4	2015-08-08 11:51
MOT test number	759220325283
Result	✓ Passed
Advice	Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3	2015-08-08 10:45
MOT test number	138980425288
Result	✗ Failed
Advice	Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Offside Rear position lamp(s) not working (1.1.A.3b)
Advice	Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2	2014-08-16 11:23
MOT test number	879388924235
Result	✓ Passed

MOT #1	2013-08-10 12:18
MOT test number	978912823296
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX60NFT
Plate since	2024-03-28
Current registration	EX60NFT
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-09-01
Last registration	2023-01-14
Complete history	See info



Registration #1	2010-09-01	21 mi
Registration #2	2013-08-10	24.389 mi
Registration #3	2014-08-16	31.768 mi
Registration #4	2015-08-08	37.697 mi
Registration #5	2015-08-08	37.697 mi
Registration #6	2016-06-07	41.723 mi
Registration #7	2016-06-10	41.723 mi
Registration #8	2016-06-10	41.723 mi
Registration #9	2016-06-10	41.723 mi
Registration #10	2016-06-10	41.723 mi
Registration #11	2016-06-10	41.723 mi
Registration #12	2016-06-10	41.723 mi
Registration #13	2016-06-10	41.723 mi
Registration #14	2016-06-10	41.723 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1347 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AL29261