





report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM
Colour	Black
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	9.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/14



Internet history

Entry 3

Date 2022-02-08

Pictures 45

Listing price View report









source: autotrader.co.uk

Entry 2

Date	2021-07-25
------	------------

Pictures 12

Listing price View report









source: cargurus.co.uk

Entry 1

2021-07-24 Date

Pictures 12

Listing price View report









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-02-11
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	8
Total items failed	12

MOT #19	2024-02-09 09:24	
MOT test number	936488566001	
Result	✓ Passed	
Next expiry date 2025-02-11		
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords	s (5.2.3 (d) (i))	

MOT #18	2023-02-08 11:09
MOT test number	590775364761
Result	✓ Passed
MOT #17	2022-02-12 08:58
MOT test number	105914681281
Result	✓ Passed

CarCheck.co.uk page 3/14



MOT #16 2022-02-11 13:57

MOT test number 608543266989

Result × Failed

Fail Offside Rear Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15 2021-05-25 13:30

MOT test number 411470026476

MOT #14 2020-06-11 07:00

MOT test number 695326276633

Result ✓ Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #13 2019-03-14 11:14

MOT test number 233448640031

Result \rightarrow Passed

CarCheck.co.uk page 4/14



MOT #12 2019-03-12 09:00

MOT test number 606113852891

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 235/40/18 (5.2.3 (d) (i))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively flexi (3.4 (b) (ii))

MOT #11 2018-10-15 08:24

MOT test number 786757205508

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin 2/3rds worn (1.1.13 (a) (ii))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2017-10-14 09:25

MOT test number 487887438898

Result ✓ Passed

MOT #9 2016-10-14 07:48

MOT test number 541398440040

Result ✓ Passed

MOT #8 2015-10-16 15:37

MOT test number 522811444467

Result

Passed

CarCheck.co.uk page 5/14



MOT test number

Result

Pass with rectification

Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Pass with rectification

Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

 MOT #6
 2015-04-29 15:23

 MOT test number
 257269515107

 Result
 ✓ Passed

 MOT #5
 2015-04-29 14:09

 MOT test number
 989579215139

 Result
 X Failed

 Fail
 Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)

 MOT #4
 2014-07-14 11:45

 MOT test number
 906515694128

 Result
 ✓ Passed

 MOT #3
 2013-08-23 10:10

 MOT test number
 497155933266

 Result
 ✓ Passed

MOT #2

MOT test number

409822292295

Result

✓ Passed

CarCheck.co.uk page 6/14



MOT #1

MOT test number

Result

Pass with rectification

Nearside Rear Stop lamp not working (1.2.1b)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	11 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NIS UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-12-29
Last registration	2024-02-09
Complete history	See info



Registration #1	2009-12-29	26 mi
Registration #2	2012-10-18	9.412 mi
Registration #3	2013-08-23	12.236 mi
Registration #4	2014-07-14	16.717 mi
Registration #5	2015-04-29	20.074 mi
Registration #6	2015-04-29	20.074 mi
Registration #7	2015-10-16	20.647 mi
Registration #8	2015-10-16	20.647 mi
Registration #9	2016-10-14	26.022 mi
Registration #10	2017-10-14	31.970 mi
Registration #11	2018-10-15	36.442 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.177 ms
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 13/14



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1326 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

Engine number 9B33524