





report date: 2024-03-28

General information

Make	ТОҮОТА
Model	COROLLA VERSO VVT-I SR
Colour	Grey
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2022-02-21


Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-06-18
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	30
Total items failed	10

MOT #18		2023-06-19 10:08
MOT test	number	392376552198
Result		✓ Passed
Next expi	ry date	2024-06-18
Advice Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))		

MOT #17		2023-06-14 11:39
MOT test	number	975614741428
Result		≍ Failed
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush s	slightly worn (5.1.2 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Fail C	Offside Front Suspension arm ball joint dust cover no longer prevents	the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush sli	ghtly worn (5.1.2 (b) (i))
Fail N	learside Front Suspension arm ball joint dust cover no longer prevent	es the ingress of dirt (5.3.4 (b)

CarCheck.co.uk page 3/14



MOT #16 2022-06-16 17:19

MOT test number 476125620911

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both side (5.1.2 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2021-08-28 11:43

MOT test number 862710218272

Result \(\sqrt{Passed} \)

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both sides (5.1.2 (b) (i))

Advice Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e))

MOT #14 2020-08-24 10:30

MOT test number 203117489944

Result \(\sqrt{Passed} \)

MOT #13 2019-08-28 15:47

MOT test number 380005542265

Result

Passed

MOT #12 2019-08-28 09:39

MOT test number 832615414080

Result X Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/14



MOT #11 2018-08-15 11:12

MOT test number 485835779372

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2017-08-31 09:38

MOT test number 212866823024

Advice FRONT BRAKE DISCS WORN

Advice REAR CHILD SEATS RESTRICTING BELT INSPECTION

Advice WIPER BLADES POOR

MOT #9 2016-08-31 10:29

MOT test number 982387340817

Result Passed

Advice Brake pad(s) wearing thin FRONT AND REAR PADS (3.5.1g)

MOT #8 2015-09-03 00:00

MOT test number 679536772105

CarCheck.co.uk page 5/14



Advice

Notice

HJ08USP report date: 2024-03-28

MOT #7 2015-03-11 15:37 797970775073 **MOT** test number Result ✓ Passed **Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f) **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Rear Direction indicators slightly discoloured (1.4.A.2f) Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

N/s/f and n/s/r tyres have cuts in sidewall but not to cords

MOT #6		2014-03-10 16:00
MOT test nu	mber	598439164076
Result		✓ Passed
MOT #5		2013-03-11 12:22
MOT test nu	mber	106700873497
Result		✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)		
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)		

CarCheck.co.uk page 6/14



Result

HJ08USP report date: 2024-03-28

✓ Passed

MOT test number

217830773060

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

 MOT #3
 2012-03-02 09:51

 MOT test number
 836822962037

 Result
 ✓ Passed

 MOT #2
 2011-03-11 15:49

 MOT test number
 119340871000

MOT test number

Result

Pass with rectification

Nearside Headlamp aim too low (1.8)

Pass with rectification

Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Pass with rectification

Offside Headlamp aim too low (1.8)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	AIR SIES
Plate since	
Current registration	OK SIEC
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-12
Last registration	2023-06-19
Complete history	See info



Registration #1	2008-03-12	26 mi
Registration #2	2011-03-11	20.892 mi
Registration #3	2012-03-02	30.486 mi
Registration #4	2013-03-11	38.968 mi
Registration #5	2014-03-10	48.546 mi
Registration #6	2015-03-11	58.990 mi
Registration #7	2015-09-03	61.834 mi
Registration #8	2016-08-31	66.873 mi
Registration #9	2017-08-31	72.806 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		10.777 mg

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles 2

Engine number 1ZZV035065