





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 ALTITUDE
Colour	Black
Year of manufacture	2006
Top speed	134 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	276 BHP
Max. torque	360 Nm at 2.500 rpm
Engine capacity	3.600 cc
Cylinders	6
Fuel type	Petrol
Consumption city	14.6 mpg
Consumption extra urban	26.7 mpg
Consumption combined	20.5 mpg
CO2 emission	331 g/km
CO2 label	М



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-10-29
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	20
Total items failed	2

MOT #18		2023-10-30 10:22
MOT test	number	507355933141
Result		✓ Passed
Next expi	ry date	2024-10-29
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both	(1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both	n (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	

MOT #17	2022-09-07 11:15
MOT test number	179598014781
Result	✓ Passed
MOT #16	2021-09-07 08:23
MOT test number	938726385542
Result	✓ Passed
MOT #15	2021-09-07 08:23
MOT test number	809850964717
Result	★ Failed
Pass with rectification Front Coil spring insecure (5.3.1 (a) (i))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT #14

MOT test number

Result

Advice Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #13 2020-08-06 09:21 **MOT** test number 634144489948 Result × Failed Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #12

MOT test number

296311072630

Result

Advice Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #11

MOT test number

675255199119

Result

Minor

Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10		2017-08-07 09:25
MOT test	number	335007117579
Result		✓ Passed
Advice	Emissions too low to read	
Advice	Nearside front tyre wearing outer	
Advice	Rear brake discs worn	
Advice	Power steering fluid level low, but not below minimum (2.3.1)	

MOT #9	2016-08-31 09:00
MOT test number	798961018166
Result	✓ Passed
MOT #8	2015-09-09 09:30
MOT test number	318195452712
Result	✓ Passed
Advice Brake pad warning lamp illuminated	

MOT #7	2014-10-04 10:10
MOT test number	396077974466
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2013-10-08 12:41
MOT test number	937841583233
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5	2012-10-06 11:02
MOT test number	527700382224
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

Advice Nearside Rear Tyre worn close to the legal I	imit (4.1.E.1)
MOT #4	2011-07-19 09:09
MOT #4 MOT test number	538870001262
Result	✓ Passed
MOT #3	2011-07-07 12:04
MOT test number	696198781166
Result	✓ Passed
MOT #2	2010-08-05 10:47
MOT test number	810627210292
Result	✓ Passed
MOT #1	2009-08-12 11:15
MOT test number	521424329284
Result	✓ Passed

MOT #1	2009-08-12 11:15
MOT test number	521424329284
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-19
Last registration	2023-10-30
Complete history	See info



Registration #1	2006-09-19	29 mi
Registration #2	2009-08-12	18.522 mi
Registration #3	2010-08-05	24.702 mi
Registration #4	2011-07-07	30.346 mi
Registration #5	2011-07-19	30.370 mi
Registration #6	2012-10-06	37.369 mi
Registration #7	2013-10-08	42.679 mi
Registration #8	2014-10-04	50.291 mi
Registration #9	2015-09-09	56.923 mi
Registration #10	2016-08-31	64.176 mi
Registration #11		11.177 es
Registration #12		71.777 es
Posistration #12		
Registration #13		11.777 es
Registration #14		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #14		11.777 es 11.777 es 11.777 es
Registration #14 Registration #15		11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16		11,777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1928 mm
Height	1703 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Multi-Point Injection
Number of doors	5
CarChack co. uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	BHK 006468