





report date: 2024-03-28

## General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	Grey
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

### Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MC	TC	history	
----	----	---------	--

MOT expiry date	2025-01-31
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	20
Total items failed	9

MOT #10	2024-01-22 14:22
MOT test number	239407847051
Result	<b>√</b> Passed
Next expiry date	2025-01-31

MOT #9	2023-01-06 12:05
MOT test number	732846637815
Result	✓ Passed

MOT #8	2022-01-31 15:24
MOT test number	157802921360
Result	✓ Passed
Advice Items removed from driver's view prior to test	

MOT #7	2021-02-01 16:04
MOT test	number 259034646047
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing low on tread /cracking (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracking and low on tread (5.2.3 (d) (ii))
Advice (ii))	Nearside Rear Tyre slightly damaged/cracking or perishing cracking and low on tread (5.2.3 (d)
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6

MOT test number

276372878046

Result

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT test number

630259744985

Result

Fail Central Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MOT #4

MOT test number

Result

MOT #3

2019-11-05 16:16

796600874643

✓ Passed

**MOT test number** 167670355848

Result X Failed

Advice Front Exhaust mounting defective (6.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))


Fail Brake servo inoperative (1.1.10 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28



MOT #1	2018-02-03 11:25
MOT test number	820191915439
Result	<b>×</b> Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Rear light cluster damaged	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Back box exhaust bracket broken	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Front bumper insecure	
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	31 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	hicton
Owner	HISLOIN

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2024-01-22
Complete history	See info



Registration #1	2014-09-30	12 mi
Registration #2	2018-02-03	29.339 mi
Registration #3	2018-02-03	29.341 mi
Registration #4	2019-10-31	38.459 mi
Registration #5	2019-11-05	38.461 mi
Registration #6	2020-10-30	39.999 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

## Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA2103961

CarCheck.co.uk page 12/12