



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Blue
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I








Internet history

Entry 1

Date	2021-06-09
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-29
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	50
Total items failed	5

MOT #18	2023-12-30 15:22
MOT test number	715070099710
Result	✓ Passed
Next expiry date	2024-12-29
Advice	Slight play in steering joints
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))
Advice	Both side sills, both side brake pipe, some suspension components corroded all
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both side front (5.3.4 (a) (i))

MOT #17	2022-03-29 18:43
MOT test number	779514201686
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Front sub frame, rear axle, front & rear brake pipe corroded
Advice	Front Outer Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))
Advice	Slight play in steering joints both side

**MOT #16**

2022-03-29 18:43

**MOT test number**

508519746713

**Result****✗ Failed****Advice** Brake disc worn, pitted or scored, but not seriously weakened front & rear (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front sub frame, rear axle, front & rear brake pipe corroded**Pass with rectification** Nearside Position lamp not working (4.2.1 (a) (ii))**Advice** Slight play in steering joints both side**Advice** Front Outer Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))**MOT #15**

2021-02-16 16:12

**MOT test number**

304913746720

**Result****✓ Passed****MOT #14**

2021-02-16 10:10

**MOT test number**

775417595813

**Result****✗ Failed****Advice** Rear Tyre slightly damaged/cracking or perishing both cracking in tread (5.2.3 (d) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2020-03-03 09:07

**MOT test number**

181092162099

**Result****✓ Passed****Advice** Centre exhaust clamp corroded

**MOT #12** 2019-02-22 09:44**MOT test number** 173936228357**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-03-05 13:40**MOT test number** 728466839401**Result** ✓ Passed**Advice** Rusty exhaust**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #10** 2018-03-05 11:50**MOT test number** 372786353488**Result** ✗ Failed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Rusty exhaust**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #9** 2017-02-24 16:33**MOT test number** 396748768374**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**Advice** Offside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

**MOT #8** 2017-02-24 12:12**MOT test number** 606888449999**Result** ✗ Failed

**Advice** Offside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

**Advice** Offside Front Tyre worn close to the legal limit Scrubbing outer edge (4.1.E.1)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Advice** Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)

**Advice** Nearside Front Tyre worn close to the legal limit Scrubbing outer edge (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit Scrubbing outer edge (4.1.E.1)

**MOT #7** 2016-02-05 11:04**MOT test number** 302893898279**Result** ✓ Passed

**Advice** Centre exhaust bracket broken

**Advice** Offside wiper blade starting to split

**Advice** Offside rear tyre getting low

**MOT #6** 2015-02-25 09:49**MOT test number** 846256655014**Result** ✓ Passed

**Notice** Right horn button seems temperamental

**Notice** Slight play in nearside front lower suspension ball joint

**Notice** Track rod end dust boots are starting deteriorate

**MOT #5** 2014-02-24 12:07**MOT test number** 197815354050**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**Notice** Both front brake discs rusty and worn on inner face**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Brake warning light on**MOT #4** 2013-02-06 09:38**MOT test number** 249157733092**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nearside screen washer jet slightly blocked**Notice** Offside front tyre worn on inner edge and close to limit**MOT #3** 2012-02-02 11:37**MOT test number** 605423432061**Result** ✓ Passed**Notice** Nearside front tyre worn on inner edge**MOT #2** 2011-02-28 15:55**MOT test number** 155359251413**Result** ✓ Passed



MOT #12010-02-25 15:15

MOT test number594586550072

Result

✓ Passed

- Notice

Offside front tyre worn on inner edge
- Notice

Nearside front tyre has a split on outer wall (not down to cords)
- Notice

Both rear tyres starting to deteriorate on outer walls
- Notice

Front number plate slightly damaged
- Notice

Nearside front tyre showed signes of run flat
- Notice

Both front tyres starting to deteriorated





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
29 December 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	29 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-01
Last registration	2023-12-30
Complete history	<a href="#">See info</a>



Registration #1	2007-03-01	19 mi
Registration #2	2010-02-25	15.675 mi
Registration #3	2011-02-28	21.409 mi
Registration #4	2012-02-02	25.750 mi
Registration #5	2013-02-06	32.213 mi
Registration #6	2014-02-24	41.689 mi
Registration #7	2015-02-25	52.697 mi
Registration #8	2016-02-05	61.142 mi
Registration #9	2017-02-24	72.387 mi
Registration #10	2017-02-24	72.387 mi
Registration #11	2018-02-24	83.632 mi
Registration #12	2019-02-24	94.877 mi
Registration #13	2020-02-24	106.122 mi
Registration #14	2021-02-24	117.367 mi
Registration #15	2022-02-24	128.612 mi
Registration #16	2023-02-24	139.857 mi
Registration #17	2024-02-24	151.102 mi
Registration #18	2025-02-24	162.347 mi
Registration #19	2026-02-24	173.592 mi
Registration #20	2027-02-24	184.837 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1393 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 062004