



YP53JXX

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE
Colour	Blue
Year of manufacture	2003
Gearbox	-

Engine & fuel consumption

Engine capacity	1.896 cc
Fuel type	Diesel
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-09
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2023-03-22
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	73
Total items failed	9

MOT #202020-11-23 14:11

MOT test number228849973543

Result✓ Passed

Next expiry date2021-11-22

- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Exhaust deteriorated
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Exhaust mounting defective (6.1.2 (a))
- Advice

Outer sills damaged

**MOT #19**

2020-11-17 11:30

**MOT test number**

529142665990

**Result****✗ Failed****MAJOR** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Exhaust deteriorated**Advice** Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Items removed from driver's view prior to test**MAJOR** Offside Headlamp levelling device inoperative (4.1.5 (a))**Advice** Outer sills damaged**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**DANGEROUS** Nearside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))



MOT #182019-05-17 15:33

MOT test number722360564997

Result

✓ Passed

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Play in steering rack inner joint(s)
- Advice

Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Play in steering rack inner joint(s)
- Advice

Rear silencer showing signs of corrosion

**MOT #17**

2019-05-10 13:54

**MOT test number**

817248497433

**Result****✗ Failed****DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))**Advice** Heater plugs warning lamp illuminated**MAJOR** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Play in steering rack inner joint(s)**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Front Nail in tyre**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Rear silencer showing signs of corrosion**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #16**

2018-05-14 16:22

**MOT test number**

723038060667

**Result****✓ Passed****Advice** Rear exhaust silencer showing signs of corrosion

**MOT #15**

2017-05-08 13:28

**MOT test number**

506257859946

**Result**

✓ Passed

**Advice**

Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #14**

2016-03-24 11:07

**MOT test number**

900757434481

**Result**

✓ Passed

**Advice**

Front Tyre worn close to the legal limit both sides (4.1.E.1)

**Advice**

Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear both sides (2.4.G.2)

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13**

2015-04-17 14:39

**MOT test number**

468807005196

**Result**

✓ Passed

**Notice**

Engine covers fitted obscuring some components in the engine bay

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice**

Under-trays fitted obscuring some underside components

**Notice**

Slight bind on offside front brakes

**Advice**

Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

**Advice**

Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #12**

2015-04-07 11:32

**MOT test number**

365887795028

**Result****✗ Failed**

- Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Front Side repeater not working (1.4.A.2c)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Nearside Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Front passenger door cannot be opened from inside the vehicle (6.2.B.1b)
- Notice** Slight bind on offside front brakes

**MOT #11**

2014-03-31 10:22

**MOT test number**

167080994408

**Result****✓ Passed**

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Notice** Under-trays fitted obscuring some underside components



**MOT #10** 2013-04-06 15:42**MOT test number** 338906993000**Result** ✓ Passed

- Notice** Advise slight corrosion on exhaust system
- Notice** Advise slight corrosion on nearside front brake disc
- Notice** Items removed from driver's view prior to test

**MOT #9** 2013-04-06 15:30**MOT test number** 739496693039**Result** ✗ Failed

- Notice** Advise slight corrosion on nearside front brake disc
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Side repeater not working (1.4.A.2c)
- Notice** Items removed from driver's view prior to test
- Notice** Advise slight corrosion on exhaust system
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2012-01-13 12:56**MOT test number** 158233612427**Result** ✓ Passed**MOT #7** 2011-01-25 09:58**MOT test number** 646215721024**Result** ✓ Passed**MOT #6** 2010-01-22 09:59**MOT test number** 181962720084**Result** ✓ Passed

**MOT #5** 2009-01-28 09:33**MOT test number** 471738529048**Result** ✓ Passed**Notice** Han d brake cable incorrectly adjusted**MOT #4** 2009-01-28 09:33**MOT test number** 321058529030**Result** ✗ Failed**Notice** Han d brake cable incorrectly adjusted**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #3** 2007-12-11 12:45**MOT test number** 611295947318**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Pass with rectification** Offside Headlamp aim too high and too far to the right. (1.8)**MOT #2** 2007-12-11 12:45**MOT test number** 434015247455**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #1** 2006-12-07 16:56**MOT test number** 532591646313**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YP53JXX
Plate since	2019-03-29
Current registration	 YP53JXX
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-10-31
Last registration	2020-11-23
Complete history	<a href="#">See info</a>



Registration #1	2003-10-31	26 mi
Registration #2	2006-12-07	28.916 mi
Registration #3	2007-12-11	35.588 mi
Registration #4	2009-01-28	45.656 mi
Registration #5	2010-01-22	52.131 mi
Registration #6	2011-01-25	58.463 mi
Registration #7	2012-01-13	64.677 mi
Registration #8	2013-04-06	87.902 mi
Registration #9	2013-04-06	87.902 mi
Registration #10	2014-03-31	99.315 mi
Registration #11	2015-05-20	101.377 mi
Registration #12	2016-05-20	101.377 mi
Registration #13	2017-05-20	101.377 mi
Registration #14	2018-05-20	101.377 mi
Registration #15	2019-05-20	101.377 mi
Registration #16	2020-05-20	101.377 mi
Registration #17	2021-05-20	101.377 mi
Registration #18	2022-05-20	101.377 mi
Registration #19	2023-05-20	101.377 mi
Registration #20	2024-05-20	101.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN