



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Silver
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.2 mpg
CO2 emission	203 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-25
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-31
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	13
Total items failed	11

MOT #19	2023-08-18 11:55
MOT test number	221477451966
Result	✓ Passed
Next expiry date	2024-08-31

MOT #18	2022-08-15 13:59
MOT test number	240009232813
Result	✓ Passed

MOT #17	2022-08-15 12:43
MOT test number	742182533324
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #16	2021-09-01 16:12
MOT test number	202556204279
Result	✓ Passed

**MOT #15** 2021-09-01 09:48**MOT test number** 146738425224**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #14** 2020-06-25 11:18**MOT test number** 273912276603**Result** ✓ Passed**MOT #13** 2020-06-25 11:18**MOT test number** 335076466066**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #12** 2019-04-10 09:29**MOT test number** 766403474755**Result** ✓ Passed**MOT #11** 2019-04-09 17:42**MOT test number** 813351585036**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Offside Front Outer Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Front Headlamp aim too low and too far to the right. (4.1.2 (a))**Fail** Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))

**MOT #10** 2019-03-18 09:51**MOT test number** 762898528058**Result** ✗ Failed**Advice** Rear rear wiper blade split**Fail** Oil leaking excessively from transmission gearbox sump (8.4.1 (a) (i))**MOT #9** 2018-03-16 10:55**MOT test number** 822615003742**Result** ✓ Passed**Advice** Oil leak on gearbox**MOT #8** 2017-03-20 14:20**MOT test number** 353354917394**Result** ✓ Passed**Advice** Exhaust back box to mid section join corroded**MOT #7** 2016-03-23 11:38**MOT test number** 148367086049**Result** ✓ Passed**MOT #6** 2015-03-13 15:03**MOT test number** 559552875090**Result** ✓ Passed**MOT #5** 2015-03-13 11:34**MOT test number** 137812075411**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #4** 2014-03-07 14:52**MOT test number** 955516164048**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2014-03-07 09:25**MOT test number** 197246964008**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2013-03-23 09:58**MOT test number** 647022983096**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2012-03-10 09:17**MOT test number** 837240072001**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside front tyre worn smooth on edges of tread



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
31 August 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	31 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-28
Last registration	2023-08-18
Complete history	See info



Registration #1	2009-03-28	18 mi
Registration #2	2012-03-10	33.914 mi
Registration #3	2013-03-23	45.283 mi
Registration #4	2014-03-07	55.613 mi
Registration #5	2014-03-07	55.616 mi
Registration #6	2015-03-13	65.635 mi
Registration #7	2015-03-13	65.635 mi
Registration #8	2016-03-23	75.291 mi
Registration #9	2017-03-20	79.395 mi
Registration #10	2018-03-16	81.560 mi
Registration #11	2019-03-18	82.916 mi
Registration #12	2020-03-20	85.277 mi
Registration #13	2020-03-20	85.277 mi
Registration #14	2020-03-20	85.277 mi
Registration #15	2020-03-20	85.277 mi
Registration #16	2020-03-20	85.277 mi
Registration #17	2020-03-20	85.277 mi
Registration #18	2020-03-20	85.277 mi
Registration #19	2020-03-20	85.277 mi
Registration #20	2020-03-20	85.277 mi
Registration #21	2020-03-20	85.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1342 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC8297788