





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	107 URBAN LITE
Colour	Red
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



OY61FTK report date: 2024-03-28

MOT history

MOT expiry date	2024-10-04
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #12	2023-10-05 12:26
MOT test number	281010281911
Result	✓ Passed
Next expiry date	2024-10-04
Advice Coil spring corroded x4 (5.3.1 (b) (i))	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources x1 (4.7.1 (b) (i))	
Advice Rear Exhaust mounting defective (6.1.2 (a))	

MOT #11		2022-09-13 12:35
MOT test	number	790378690368
Result		✓ Passed
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Coil spring corroded x4 (5.3.1 (b) (i))	

MOT #10	2021-08-17 10:12
MOT test number	949061755624
Result	<b>✓</b> Passed
Advice Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Rear Exhaust mounting defective (6.1.2 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

640030489406

Result

Advice (a) (i))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT test number

856026143542

Result

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice
(a) (i))

Advice

Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7** 2019-07-31 15:19 **MOT** test number 762667519845 Result ✓ Passed **MOT #6** 2019-07-30 15:10 **MOT** test number 519176455744 Result × Failed **Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f)) Offside Rear Brake pipe excessively corroded (1.1.11 (c)) Fail

MOT #5

MOT test number

616952261134

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



Result

OY61FTK
report date: 2024-03-28

✓ Passed

MOT #4	2017-08-24 13:05
MOT test number	778810730397
Result	✓ Passed
MOT #3	2016-08-22 13:21
MOT test number	187320043729
Result	✓ Passed
MOT #2	2015-08-24 10:43
MOT test number	799676331588
Result	✓ Passed
MOT #1	2014-08-27 14:27
MOT test number	575779734222

CarCheck.co.uk page 5/12



OY61FTK
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	4 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		IGEOT
********		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-28
Last registration	2023-10-05
Complete history	See info



Registration #1	2011-09-28	13 mi
Registration #2	2014-08-27	15.207 mi
Registration #3	2015-08-24	21.925 mi
Registration #4	2016-08-22	25.792 mi
Registration #5	2017-08-24	30.501 mi
Registration #6	2018-08-20	37.272 mi
Registration #7	2019-07-30	45.201 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 mi
Registration #12		11.117 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



OY61FTK report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

- C		_		
- I )ım	ension	SW	weiat	٦t
	ווטוכוום	3 UX	WEIGH	

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

### Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7010031

CarCheck.co.uk page 12/12