






report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO 3100 SPORTIVE S/S L2H1 3100 SPORTIVE S/S
Colour	White
Year of manufacture	2019
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 2

Date 2021-09-23

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date 2021-08-30	
-----------------	--

Pictures 10

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/10



DS69UHZ report date: 2024-03-28

MOT history

MOT expiry date	2024-11-13
MOT pass rate	100 %
MOT passed	2
Failed MOT tests	0
Total advice items	1
Total items failed	0

MOT #2	2023-11-14 12:54
MOT test number	180680911875
Result	✓ Passed
Next expiry date	2024-11-13
Advice Offside Front Anti-roll bar linkage pin or bush worn but not result (a) (i))	Iting in excessive movement (5.3.4

MOT #1	2022-10-12 07:27
MOT test number	102077760367
Result	✓ Passed

CarCheck.co.uk page 3/10



DS69UHZ report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

2000000	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	JK UK
Plate since	
Current registration	AIR.
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2019-09-27
Last registration	2023-11-14
Complete history	See info



Registration #1	2019-09-27	21 mi
Registration #2		71.777 es
Registration #3		11.777 es
Registration #4		71.777 66
Registration #5		11.777 es

More info >

CarCheck.co.uk page 9/10



DS69UHZ report date: 2024-03-28

	Dimensions	s &	weight
--	------------	-----	--------

Width	2204 mm
Height	1935 mm
Length	5309 mm
Kerb weight	1685 kg
Max. allowed weight	3100 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	3
Engine number	10DY3M4010004 O4I

CarCheck.co.uk page 10/10