



General information

| | |
|---------------------|---------------------|
| Make | KIA |
| Model | VENGA 3 ECODYNAMICS |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 114 mph |
| 0 - 60 mph | 10.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 123 BHP |
| Max. torque | 156 Nm at 4.200 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 39.8 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





Internet history

Entry 3

| | |
|---------------|-----------------------------|
| Date | 2021-02-12 |
| Pictures | 30 |
| Listing price | View report |



source: yesauto.com

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-01-21 |
| Pictures | 1 |
| Listing price | View report |



source: yesauto.com

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-21 |
| Pictures | 16 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-25 |
| MOT pass rate | 78 % |
| MOT passed | 7 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #9 | 2023-05-16 14:38 |
| MOT test number | 248069720673 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-25 |
| Advice | Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii)) |

| | |
|-----------------|--|
| MOT #8 | 2022-05-26 11:40 |
| MOT test number | 898408050857 |
| Result | ✓ Passed |
| Minor | Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |

| | |
|-----------------|--|
| MOT #7 | 2022-05-25 12:16 |
| MOT test number | 766610463933 |
| Result | ✗ Failed |
| Fail | Windscreen washer not working (3.5 (a)) |
| Minor | Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |

| | |
|-----------------|------------------|
| MOT #6 | 2021-05-20 16:19 |
| MOT test number | 774333300675 |
| Result | ✓ Passed |

**MOT #5** 2020-05-26 13:51**MOT test number** 664061910977**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn low (5.2.3 (e))**Advice** Brake disc worn, pitted or scored, but not seriously weakened all brake disks lipped (1.1.14 (a) (ii))**MOT #4** 2019-03-04 10:16**MOT test number** 597330964493**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))**MOT #3** 2018-03-28 09:18**MOT test number** 439378959777**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to the legal limit Tyre low on tread @ 3 mm close to legal limit of 1.6 mm and unevenly worn out on the inner edge. (4.1.E.1)**Advice** Offside Front Inner Tyre worn close to the legal limit Tyre tread low @ 3 mm close to the legal limit of 1.6 mm and unevenly worn out on the inner edge. (4.1.E.1)**MOT #2** 2018-03-28 09:18**MOT test number** 669491727289**Result** ✗ Failed**Pass with rectification** Nearside Front Outer Windscreen wiper does not clear the windscreen effectively Both front wipers worn / ripped , at the end of their service life. (8.2.2)**Advice** Offside Front Inner Tyre worn close to the legal limit Tyre tread low @ 3 mm close to the legal limit of 1.6 mm and unevenly worn out on the inner edge. (4.1.E.1)**Advice** Nearside Front Inner Tyre worn close to the legal limit Tyre low on tread @ 3 mm close to legal limit of 1.6 mm and unevenly worn out on the inner edge. (4.1.E.1)



| | |
|---|------------------|
| MOT #1 | 2017-03-13 15:02 |
| MOT test number | 605395425896 |
| Result | ✓ Passed |
| <div><div>Advice</div>Front Windscreen has damage to an area less than a 10mm circle within zone 'A' light scratches all over screen (8.3.1a)</div> | |



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
25 May 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 367 |
| MOT expiry date | 25 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this KIA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | AY14YNE |
| Plate since | 2019-09-29 |
| Current registration | AY14YNE |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2014-03-31 |
| Last registration | 2023-05-16 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-03-31 | 27 mi |
| Registration #2 | 2017-03-13 | 24.452 mi |
| Registration #3 | 2018-03-28 | 31.227 mi |
| Registration #4 | 2018-03-28 | 31.227 mi |
| Registration #5 | 2019-03-04 | 39.526 mi |
| Registration #6 | 2020-05-26 | 49.953 mi |
| Registration #7 | 2020-05-26 | 55.277 mi |
| Registration #8 | 2020-05-26 | 55.277 mi |
| Registration #9 | 2020-05-26 | 55.277 mi |
| Registration #10 | 2020-05-26 | 55.277 mi |
| Registration #11 | 2020-05-26 | 55.277 mi |
| Registration #12 | 2020-05-26 | 55.277 mi |
| Registration #13 | 2020-05-26 | 55.277 mi |

More info >



Car features

The KIA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 85% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1765 mm |
| Height | 1600 mm |
| Length | 4068 mm |
| Wheel base | 2615 mm |
| Kerb weight | 1355 kg |
| Max. allowed weight | 1710 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | G4FCEZ328651 |