



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE SL OASIS 16V
Colour	Green
Year of manufacture	2005
Top speed	119 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	152 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	163 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-01-26
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	48
Total items failed	15

MOT #24 2023-01-27 10:19

MOT test number 671118283311

Result ✓ Passed

Next expiry date 2024-01-26

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside (1.1.14 (a) (ii))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Play in steering rack inner joint(s) Nearside & Offside

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside (1.1.14 (a) (ii))

MOT #23 2023-01-27 10:19

MOT test number 692218652876

Result ✗ Failed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside (1.1.14 (a) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Nearside & Offside (1.1.14 (a) (ii))

**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Play in steering rack inner joint(s) Nearside & Offside

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #22**

2022-01-12 12:32

**MOT test number**

994725533568

**Result**

✓ Passed

**Advice** Nearside Rear disc slight rusted**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear disc slight rusted**Advice** Offside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #21**

2022-01-11 16:28

**MOT test number**

373288246528

**Result**

✗ Failed

**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear disc slight rusted**Advice** Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear disc slight rusted**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #20**

2021-01-20 11:49

**MOT test number**

366756245000

**Result**

✓ Passed

**Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Play in steering rack inner joint(s)

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

**Advice**

Vehicle shows slight damage to nearside front wing

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

**MOT #19**

2021-01-20 11:49

**MOT test number**

762758045662

**Result**

✗ Failed

**Advice**

Vehicle shows slight damage to nearside front wing

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

**Pass with rectification**

Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Play in steering rack inner joint(s)

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

**Pass with rectification**

Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #18**

2020-01-21 15:34

**MOT test number**

594595205873

**Result**

✓ Passed

**MOT #17**

2020-01-20 09:13

**MOT test number**

973595206736

**Result****✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #16**

2019-01-12 09:34

**MOT test number**

757301326495

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2018-01-22 11:27

**MOT test number**

936687786211

**Result****✓ Passed****MOT #14**

2018-01-20 09:40

**MOT test number**

919822060535

**Result****✗ Failed****Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Rear rear brake binding (3.7.B.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #13**

2017-01-23 16:03

**MOT test number**

502682606489

**Result**

✓ Passed

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #12**

2017-01-23 11:02

**MOT test number**

802140758168

**Result**

✗ Failed

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11**

2016-01-15 08:54

**MOT test number**

305396554202

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10**

2016-01-15 08:54

**MOT test number**

654216603294

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #9** 2015-01-06 11:49**MOT test number** 827966205021**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #8** 2015-01-06 11:49**MOT test number** 299316705020**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #7** 2014-01-15 11:42**MOT test number** 409285714006**Result** ✓ Passed**MOT #6** 2013-01-18 16:08**MOT test number** 229318613083**Result** ✓ Passed**MOT #5** 2012-01-16 10:35**MOT test number** 925776212067**Result** ✓ Passed**MOT #4** 2011-01-12 11:55**MOT test number** 195042511497**Result** ✓ Passed



MOT #3	2010-01-11 14:41
MOT test number	774551710081
Result	✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #2	2009-01-12 14:55
MOT test number	112732519436
Result	✓ Passed

MOT #1	2008-01-18 09:32
MOT test number	280448318082
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
31 December 2023

✕  
MOT

Expired:  
26 January 2024

Tax status	Expired at 31 December 2023
Days left	120 days too late
MOT expiry date	26 January 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>REDACTED</b>
Plate since	2019-09-29
Current registration	<b>REDACTED</b>
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-01-20
Last registration	2023-01-27
Complete history	<a href="#">See info</a>



Registration #1	2005-01-20	27 mi
Registration #2	2008-01-18	14.762 mi
Registration #3	2009-01-12	19.008 mi
Registration #4	2010-01-11	22.990 mi
Registration #5	2011-01-12	25.181 mi
Registration #6	2012-01-16	28.114 mi
Registration #7	2013-01-18	31.422 mi
Registration #8	2014-01-15	33.109 mi
Registration #9	2015-01-06	38.931 mi
Registration #10	2016-01-15	46.619 mi
Registration #11	2016-01-15	46.619 mi
Registration #12	2017-01-23	54.508 mi
Registration #13	2018-01-20	55.337 mi
Registration #14	2019-01-20	55.337 mi
Registration #15	2020-01-20	55.337 mi
Registration #16	2021-01-20	55.337 mi
Registration #17	2022-01-20	55.337 mi
Registration #18	2023-01-20	55.337 mi
Registration #19	2023-01-20	55.337 mi
Registration #20	2023-01-20	55.337 mi
Registration #21	2023-01-20	55.337 mi
Registration #22	2023-01-20	55.337 mi
Registration #23	2023-01-20	55.337 mi
Registration #24	2023-01-20	55.337 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1458 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1225 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D229186