




report date: 2024-03-29

General information

| | |
|---------------------|--------------------------------|
| Make | VAUXHALL |
| Model | VIVARO L2H1 2900 SPORTIVE CDTI |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 100 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 118 BHP |
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.3 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 174 g/km |
| CO2 label | H |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-01-18 |
| Pictures | 6 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-10 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 0 |

| | |
|------------------|---|
| MOT #4 | 2024-01-10 14:59 |
| MOT test number | 565502576852 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-10 |
| Advice | Nearside Front Play in steering rack inner joint(s) |
| Minor | Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i)) |

| | |
|-----------------|---|
| MOT #3 | 2023-01-10 16:20 |
| MOT test number | 447138899311 |
| Result | ✓ Passed |
| Advice | Rear Tyre slightly damaged/cracking or perishing ns and os outer walls scuffed (5.2.3 (d) (ii)) |
| Advice | Nearside Front mirror cover missing |

| | |
|-----------------|---|
| MOT #2 | 2023-01-10 12:21 |
| MOT test number | 952314935795 |
| Result | ✗ Failed |
| Advice | Rear Tyre slightly damaged/cracking or perishing ns and os outer walls scuffed (5.2.3 (d) (ii)) |
| MAJOR | Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) |
| Advice | Nearside Front mirror cover missing |



| | |
|-----------------|--|
| MOT #1 | 2022-01-11 14:22 |
| MOT test number | 867053462315 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
10 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 306 |
| MOT expiry date | 10 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2019-07-12 |
| Last registration | 2024-01-10 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-07-12 | 15 mi |
| Registration #2 | 2022-01-11 | 57.356 mi |
| Registration #3 | 2022-01-11 | 57.356 mi |
| Registration #4 | 2022-01-11 | 57.356 mi |
| Registration #5 | 2022-01-11 | 57.356 mi |
| Registration #6 | 2022-01-11 | 57.356 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★ |
| Adult | 52% |
| Children | 91% |
| Pedestrian | 53% |
| Safety systems | 57% |
| Overall rating | 61% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2283 mm |
| Height | 1971 mm |
| Length | 5398 mm |
| Kerb weight | 1750 kg |
| Max. allowed weight | 3030 kg |

Additional information

| | |
|--------------------|---------------------|
| Fuel tank capacity | 80 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | R9M H4 - C228991LWZ |