



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	Red
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 2.700 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-27
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	9
Total items failed	2

MOT #12 2023-06-28 11:57

MOT test number 789728234899

Result ✓ Passed

Next expiry date 2024-06-27

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #11 2022-02-11 10:16

MOT test number 781478785948

Result ✓ Passed

MOT #10 2020-12-16 11:27

MOT test number 916878934421

Result ✓ Passed

MOT #9 2019-11-09 12:29

MOT test number 630283279673

Result ✓ Passed

**MOT #8** 2018-11-09 16:23**MOT test number** 487416661441**Result** ✓ Passed**Advice** Low emissions vehicle, no values recorded**MOT #7** 2018-11-06 13:07**MOT test number** 556567274229**Result** ✗ Failed**Advice** Low emissions vehicle, no values recorded**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #6** 2017-10-20 13:19**MOT test number** 441323469615**Result** ✓ Passed**MOT #5** 2017-10-12 08:26**MOT test number** 188083148926**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit tyre is starting to go out of shape & has screw in it (4.1.E.1)**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**MOT #4** 2016-11-04 14:59**MOT test number** 980765343326**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2015-11-06 16:01
MOT test number	540947411759
Result	✓ Passed

MOT #2	2015-11-06 10:32
MOT test number	886133118968
Result	✗ Failed
<div><div>Fail</div>Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)</div>	

MOT #1	2014-10-10 17:06
MOT test number	838683584212
Result	✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YK61TEY
Plate since	2019-09-29
Current registration	YK61TEY
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-11-08
Last registration	2023-06-28
Complete history	See info



Registration #1	2011-11-08	25 mi
Registration #2	2014-10-10	34.052 mi
Registration #3	2015-11-06	48.722 mi
Registration #4	2015-11-06	48.722 mi
Registration #5	2016-11-04	61.297 mi
Registration #6	2017-10-12	69.010 mi
Registration #7	2017-10-20	69.269 mi
Registration #8	2019-06-28	75.277 mi
Registration #9	2019-06-28	75.277 mi
Registration #10	2019-06-28	75.277 mi
Registration #11	2019-06-28	75.277 mi
Registration #12	2019-06-28	75.277 mi
Registration #13	2019-06-28	75.277 mi
Registration #14	2019-06-28	75.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	71667897
---------------	----------