




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VIVARO L1H1 2900 SPORTIVE CDTI
Colour	Silver
Year of manufacture	2017
Top speed	100 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-08-19
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-06-23
Pictures	12
Listing price	View report



AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

[aacars.com](https://www.aacars.com)

source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-08-04
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #6	2023-07-14 15:27
MOT test number	937464800258
Result	✓ Passed
Next expiry date	2024-08-04
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5	2022-08-04 15:57
MOT test number	183487143818
Result	✓ Passed
Advice	Rear brake discs corroded and pads worn low

MOT #4	2021-08-05 10:33
MOT test number	224900844964
Result	✓ Passed

**MOT #3** 2021-08-04 08:17**MOT test number** 770028005197**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #2** 2020-12-31 15:08**MOT test number** 736944362053**Result** ✓ Passed**MOT #1** 2020-06-06 05:13**MOT test number** 802389861881**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

X

Untaxed

Tax expired:
7 February 2024

✓

MOT

Expires:
4 August 2024

Tax status	Expired at 7 February 2024
Days left	83 days too late
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VO17HHP
Plate since	2019-06-29
Current registration	 VO17HHP
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-06-14
Last registration	2023-07-14
Complete history	See info



Registration #1	2017-06-14	10 mi
Registration #2	2020-12-31	25.002 mi
Registration #3	2020-12-31	25.002 mi
Registration #4	2021-08-04	26.657 mi
Registration #5	2020-12-31	25.002 mi
Registration #6	2020-12-31	25.002 mi
Registration #7	2020-12-31	25.002 mi
Registration #8	2020-12-31	25.002 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4998 mm
Wheel base	3098 mm
Kerb weight	1725 kg
Max. allowed weight	2960 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	R9M MK - C022412LWZ