



report date: 2024-03-29

General information

Make	BMW
Model	120 520D M SPORT
Colour	Blue
Year of manufacture	2014
Top speed	145 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-05-29
Pictures	66
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-05
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #10	2024-03-02 10:25
MOT test number	815693121305
Result	✓ Passed
Next expiry date	2025-03-05
Advice	Offside Play in steering rack inner joint(s)
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9	2023-03-04 09:12
MOT test number	682351414172
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-03-05 11:14
MOT test number	810094061029
Result	✓ Passed

**MOT #7** 2021-03-04 17:31**MOT test number** 900989250468**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-02-26 12:44**MOT test number** 634973752620**Result** ✓ Passed**Advice** Rear both tyres on 2.8 mm thread depth.**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2019-02-22 15:24**MOT test number** 158954110682**Result** ✓ Passed**MOT #4** 2019-02-22 13:08**MOT test number** 505374839525**Result** ✗ Failed**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))



MOT #3	2018-03-06 11:03
MOT test number	576607276734
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front slight run out at the front brakes which is not evident on a road test.

MOT #2	2018-02-28 12:03
MOT test number	968362564564
Result	✗ Failed
Fail	Front brake application uneven (3.7.B.2)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2017-02-23 16:07
MOT test number	851366529250
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
5 March 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	5 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-05
Last registration	2024-03-02
Complete history	<a href="#">See info</a>



Registration #1	2014-03-05	7 mi
Registration #2	2017-02-23	26.277 mi
Registration #3	2018-02-28	31.055 mi
Registration #4	2018-03-06	31.126 mi
Registration #5	2019-02-22	36.678 mi
Registration #6	2019-02-22	36.678 mi
Registration #7	2019-03-20	36.678 mi
Registration #8	2019-03-20	36.678 mi
Registration #9	2019-03-20	36.678 mi
Registration #10	2019-03-20	36.678 mi
Registration #11	2019-03-20	36.678 mi
Registration #12	2019-03-20	36.678 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1860 mm
Height	1475 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1630 kg
Max. allowed weight	2240 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	90219012