





General information

Make	FIAT
Model	PUNTO POP
Colour	Black
Year of manufacture	2013
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1	
Date	
Pictures	

2022-08-03

16

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-11
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #10	2023-08-10 09:40
MOT test number	280492434754
Result	🗸 Passed
Next expiry date	2024-08-11
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice O/s/f day time running light on	

МОТ #9	2022-08-12 07:39
MOT test number	284904446287
Result	✓ Passed

MOT #8		2021-12-06 12:21
MOT test	number	181320717057
Result		✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both front. (1.3	1.14 (a) (ii))
Advice	Rear exhaust box corroded.	
Advice	Coil spring corroded Both rear. (5.3.1 (b) (i))	
Minor front. (2.1	Track rod end ball joint dust cover damaged or deteriorated, but preventing th .3 (g) (i))	ne ingress of dirt Both



RJ13RCY
report date: 2024-03-28

MOT #7	2021-12-04 11:02	
MOT test number	516773935118	
Result	🗙 Failed	
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))		
Advice Coil spring corroded Both rear. (5.3.1 (b) (i))		
Minor Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both front. (2.1.3 (g) (i))		
FailOffside Rear Direction indicator incorrect colour (4.4.3 (a))		
Fail Nearside Front Headlamp aim too high (4.1.2 (a))		
Advice Brake disc worn, pitted or scored, but not seriously weakened Both front. (1.1.14)	4 (a) (ii))	
Advice Rear exhaust box corroded.		

МОТ #6	2020-12-11 10:57
MOT test number	769976649621
Result	✓ Passed

MOT #5	2020-12-09 12:45
MOT test number	277864481557
Result	🗙 Failed
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

MOT #4	2019-07-04 10:10
MOT test number	496041601946
Result	✓ Passed
MOT #2	2010 07 10 00.20

101 #5	2010-07-10 00.50
MOT test number	293954341224
Result	✓ Passed





MOT #2	2017-07-04 09:38
MOT test number	366575226297
Result	✓ Passed
MOT #1	2016-07-07 13:17
MOT test number	789462921211
Result	✓ Passed



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 11 August 2024	✓ МОТ
Tax status			Valid until 1 August
Days left			95
MOT expiry date			11 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-07-31
Last registration	2023-08-10
Complete history	<u>See info</u>



Registration #1	2013-07-31	6 mi
Registration #2	2016-07-07	17.784 mi
Registration #3	2017-07-04	23.694 mi
Registration #4	2018-07-10	30.177 mi
Registration #5	2019-07-04	33.299 mi
Registration #6	2020-12-09	36.384 mi
Registration #7		11.117 mi
Registration #8		10.000 mil
Registration #9		11.777 mi
Registration #9 Registration #10		10.000 est
		10.000 est 10.000 est 10.000 est

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	0596130