



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D5 R-DESIGN AWD
Colour	Black
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-31
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	5

MOT #14	2024-02-01 16:54
MOT test number	331995383590
Result	✓ Passed
Next expiry date	2025-01-31

MOT #13	2023-01-25 09:31
MOT test number	534172465320
Result	✓ Passed
Advice	Outer sill covers fitted. Unable to make full assessment of sills
Advice	Under engine cover fitted. Unable to make full assessment of components
Advice	Engine bay covers fitted. Unable to make full assessment of components

**MOT #12**

2022-01-21 09:40

MOT test number

626674645279

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))**Advice** Offside Rear tyre worn low**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2022-01-19 10:35

MOT test number

593362107253

Result

✗ Failed

Advice Nearside Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear tyre worn low**MOT #10**

2021-01-29 14:56

MOT test number

685929527315

Result

✓ Passed

**MOT #9** 2020-12-18 15:05**MOT test number** 241893899627**Result** ✗ Failed**Fail** Offside Rear Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**Fail** Nearside Rear Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**MOT #8** 2019-04-26 09:54**MOT test number** 958169325925**Result** ✓ Passed**Advice** N/S/F TYRE SLIGHT NICK / DAMAGE OUTER WALL**MOT #7** 2018-05-02 11:45**MOT test number** 387250687354**Result** ✓ Passed**MOT #6** 2018-05-02 11:45**MOT test number** 462041710366**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #5** 2017-05-05 09:25**MOT test number** 887424960754**Result** ✓ Passed**Advice** N/s & o/s/r brake discs worn inner faces**Advice** Both n/s & o/s/r tyres slight wearing inner edges

**MOT #4** 2016-05-12 11:19**MOT test number** 393960597089**Result** ✓ Passed**Advice** Under tray fitted and engine cover**MOT #3** 2015-05-08 09:46**MOT test number** 737188525178**Result** ✓ Passed**MOT #2** 2014-05-16 11:10**MOT test number** 368136434194**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2014-04-17 14:50**MOT test number** 466187004127**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Notice** Play in steering rack inner joint(s)**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-20
Last registration	2024-02-01
Complete history	See info



Registration #1	2011-04-20	15 mi
Registration #2	2014-04-17	48.582 mi
Registration #3	2014-05-16	49.472 mi
Registration #4	2015-05-08	56.563 mi
Registration #5	2016-05-12	61.833 mi
Registration #6	2017-05-05	67.430 mi
Registration #7	2018-05-02	69.817 mi
Registration #8	2018-05-02	69.817 mi
Registration #9	2019-05-02	71.277 mi
Registration #10	2020-05-02	72.737 mi
Registration #11	2021-05-02	74.197 mi
Registration #12	2022-05-02	75.657 mi
Registration #13	2023-05-02	77.117 mi
Registration #14	2024-02-01	78.577 mi
Registration #15	2024-02-01	78.577 mi
Registration #16	2024-02-01	78.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	913072