





General information

| Make | MERCEDES-BENZ |
|---------------------|-----------------------------|
| Model | CLS CLS220 BLUETEC AMG LINE |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 138 mph |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| Power | 174 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.400 rpm |
| Engine capacity | 2.143 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |





Internet history

Entry 2 Date

Pictures

2022-01-26 11

Listing price

View report



source: cargurus.co.uk

| Entry 1 | | |
|---------------|-------------|--|
| Date | 2022-01-25 | |
| Pictures | 11 | |
| Listing price | View report | |
| | | |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-01-25 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 2 |

| MOT #8 | 2024-01-26 14:40 | |
|---|------------------|--|
| MOT test number | 156908280250 | |
| Result | 🗸 Passed | |
| Next expiry date | 2025-01-25 | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice Offside Parking brake efficiency only just met. It would appear that the braking system requires | | |
| adjustment or repair. (1.4.2 (a) (i)) | | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |

| MOT #7 | | 2023-09-07 15:15 |
|----------|---|------------------|
| MOT test | t number | 950345293606 |
| Result | | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |
| Minor | Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i)) | |
| Advice | Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c)) | |
| Advice | Emission too clean to be tested | |

| МОТ #6 | 2022-09-08 14:49 |
|-----------------|------------------|
| MOT test number | 704362636306 |
| Result | ✓ Passed |





| MOT #5 | 2022-03-02 15:32 |
|-----------------|------------------|
| MOT test number | 438799859541 |
| Result | ✓ Passed |
| | |
| МОТ #4 | 2021-07-07 14:51 |
| MOT test number | 926034311269 |
| Result | ✓ Passed |
| | |
| МОТ #3 | 2020-11-12 11:29 |
| MOT test number | 939042204272 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2018-11-09 14:15 |
| MOT test number | 394758603362 |

| MOT test number | 394758603362 |
|-----------------|--------------|
| Result | ✓ Passed |
| | |

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

| MOT #1 | 2018-11 | -09 14:15 |
|--|---|-----------------|
| MOT test number | 61547 | 75764300 |
| Result | | X Failed |
| Pass with rectification | Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i)) | | |
| Pass with rectification | Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) | |



Tax & MOT check

| ✓ Taxed Tax due: 1 September 2024 | ✓ MOT Expires: 25 January 2025 |
|--|---|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 25 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FEIDO |
| Category | K ATAPE |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Category | AMPLE |
| Туре | |

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| *********** | |
|--|-------------|
| ACCOUNTS AND A DESCRIPTION OF A DESCRIPR | |
| | |
| And a second sec | |
| ********** | |
| ******** | |
| | More info > |
| | More into > |
| Plate changes | |
| See in this check if this MERCEDES-BENZ had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Correct registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 11 |
| First mileage registration | 2015-05-28 |
| Last registration | 2024-01-26 |
| Complete history | See info |



| Registration #1 | 2015-05-28 | 19 mi |
|------------------|------------|------------|
| Registration #2 | 2018-11-09 | 42.866 mi |
| Registration #3 | 2018-11-09 | 42.866 mi |
| Registration #4 | 2020-11-12 | 67.831 mi |
| Registration #5 | 2021-07-07 | 68.410 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 11.777 mi |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| S0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|------------------------|
| Adult | 93% |
| Children | 81% |
| Pedestrian | 67% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | <u>see crash video</u> |



| Dimensions & weight | | |
|------------------------|------------------|------------|
| Width | 2075 mm | |
| Height | 1418 mm | |
| Length | 4937 mm | |
| Wheel base | 2874 mm | |
| Kerb weight | 1790 kg | |
| Max. allowed weight | 2275 kg | |
| Additional information | | |
| Fuel tank capacity | 59 I | |
| Fuel delivery | Direct Injection | |
| Number of doors | 4 | |
| CarCheck.co.uk | | page 11/11 |

| Number of seats | 4 |
|-----------------|----------------|
| Number of axles | 2 |
| Engine number | 65192432556533 |