



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Black
Year of manufacture	2008
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	95 BHP
Max. torque	125 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-10
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-13
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	17
Total items failed	9

MOT #18 2023-05-30 14:24

MOT test number 600710961631

Result ✓ Passed

Next expiry date 2024-06-13

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** O/s rear shocker cover insecure**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17 2023-05-30 14:24

MOT test number 758709063212

Result ✗ Failed**Advice** O/s rear shocker cover insecure**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

MOT #16 2022-06-14 14:40

MOT test number 856196781432

Result ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2022-06-14 12:41**MOT test number** 780840052358**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #14** 2021-05-13 14:21**MOT test number** 959347707175**Result** ✓ Passed**MOT #13** 2020-05-14 13:56**MOT test number** 929500907492**Result** ✓ Passed**MOT #12** 2020-05-14 09:09**MOT test number** 643753809375**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2019-06-24 09:07**MOT test number** 444489571190**Result** ✓ Passed

**MOT #10** 2018-06-13 09:44**MOT test number** 920667891907**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2017-06-12 13:55**MOT test number** 764505750410**Result** ✓ Passed**Advice** Mil light on**Advice** O/s/r tyre worn to 3mm**MOT #8** 2017-06-12 09:06**MOT test number** 113673071830**Result** ✗ Failed**Advice** Mil light on**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** O/s/r tyre worn to 3mm**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #7** 2016-06-06 08:56**MOT test number** 607368401164**Result** ✓ Passed**MOT #6** 2015-06-17 10:22**MOT test number** 185798265120**Result** ✓ Passed

**MOT #5** 2014-05-29 10:29**MOT test number** 445949844124**Result** ✓ Passed**MOT #4** 2013-06-20 09:47**MOT test number** 715151273163**Result** ✓ Passed**Notice** O/s/r tyre starting to wear on inner edge 4mm**MOT #3** 2012-06-14 12:59**MOT test number** 419686862147**Result** ✓ Passed**MOT #2** 2011-06-16 15:01**MOT test number** 959827261180**Result** ✓ Passed**MOT #1** 2011-06-16 12:25**MOT test number** 337427761116**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Notice** O/s/r tyre worn on inner & outer edges**Notice** N/s/r seat belt buckle case cracked but not affecting operation of buckle



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-07-28
Last registration	2023-05-30
Complete history	See info



Registration #1	2008-07-28	9 mi
Registration #2	2011-06-16	38.749 mi
Registration #3	2011-06-16	38.749 mi
Registration #4	2012-06-14	40.135 mi
Registration #5	2013-06-20	43.612 mi
Registration #6	2014-05-29	47.096 mi
Registration #7	2015-06-17	49.121 mi
Registration #8	2016-06-06	51.698 mi
Registration #9	2017-06-12	54.685 mi
Registration #10	2017-06-12	54.687 mi
Registration #11	2018-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2020-05-29	55.277 mi
Registration #14	2021-05-29	55.277 mi
Registration #15	2022-05-29	55.277 mi
Registration #16	2023-05-30	55.277 mi
Registration #17	2023-05-30	55.277 mi
Registration #18	2023-05-30	55.277 mi
Registration #19	2023-05-30	55.277 mi
Registration #20	2023-05-30	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1055 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

G4EE7761955