





report date: 2024-03-28

General information

Make	SUZUKI
Model	VITARA SZ-T
Colour	Grey
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/10



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-30
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	4
Total items failed	7

MOT #8	2023-10-31 16:44
MOT test number	286442414717
Result	✓ Passed
Next expiry date	2024-10-30

MOT #7	2023-10-31 10:30
MOT test number	697741669153
Result	X Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2022-12-05 14:43
MOT test number	783920857544
Result	✓ Passed

MOT #5	2021-10-29 08:26
MOT test number	266147889926
Result	✓ Passed

MOT #4	2020-09-24 08:28
MOT test number	313840062494
Result	✓ Passed

CarCheck.co.uk page 2/10



EK16ZZH report date: 2024-03-28

MOT #3 2019-04-02 12:28

MOT test number 307382891281

Result ✓ Passed

Advice Brake pedal wearing smooth (1.1.2 (c))

MOT #2 2019-04-02 08:47

MOT test number 534792849201

Result X Failed

Advice Washer bottle cap missing

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1 2019-03-28 09:45

MOT test number 964984112251

Result × Failed

Fail Central Rear Seat belt missing (7.1.2 (a))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Washer bottle cap missing

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/10



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 4/10



report date: 2024-03-28

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 7/10



EK16ZZH report date: 2024-03-28

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-31
Last registration	2023-10-31
Complete history	See info



Registration #1	2016-03-31	10 mi
Registration #2	2019-03-28	29.221 mi
Registration #3	2019-04-02	29.385 mi
Registration #4	2019-04-02	29.392 mi
Registration #5	2020-09-24	37.293 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	76%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1775 mm
Height	1610 mm
Length	4175 mm
Wheel base	2500 mm
Kerb weight	1150 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	M16A-2060332

CarCheck.co.uk page 10/10