



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V I-VTEC SE
Colour	Silver
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	174 Nm at 4.300 rpm
Engine capacity	1.799 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2022-02-20
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-04-21
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	27
Total items failed	0

MOT #14 2022-04-22 12:37

MOT test number 317127833621

Result ✓ Passed

Next expiry date 2023-04-21

Advice Some corrosion to rear axle and associated components

Advice Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2021-03-11 14:18

MOT test number 903103357197

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Tyre worn close to legal limit/worn on edge both front tyres bald on inner, almost to cords (5.2.3 (e))

Advice Exhaust has a minor leak of exhaust gases coming from front (6.1.2 (a))

MOT #12 2020-03-10 12:47

MOT test number 196766945078

Result ✓ Passed

**MOT #11**

2020-03-09 13:08

MOT test number

277078633795

Result

✗ Failed

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #10**

2019-03-22 12:42

MOT test number

855421105942

Result

✓ Passed

Advice Offside Rear wheel arch slightly corroded**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear wheel arch slightly corroded**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))**MOT #9**

2019-03-13 09:48

MOT test number

555277739587

Result

✗ Failed

MAJOR Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting outer sill (6.2.2 (d) (i))**Advice** Offside Rear wheel arch slightly corroded**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear wheel arch slightly corroded**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill (5.3.6 (a) (i))**MAJOR** Nearside Rear Anti-roll bar pin or bush excessively worn anti roll D bush (5.3.4 (a) (i))

**MOT #8** 2018-03-08 09:48**MOT test number** 700173802251**Result** ✓ Passed

- Advice** Underside of vehicle has slight surface corrosion
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear nearside and offside rear tyres slightly deteriorated
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear nearside and offside rear wheel arches has slight surface corrosion
- Advice** Rear Anti-roll bar linkage has slight play in a ball joint both nearside and offside (2.4.G.2)

MOT #7 2017-03-15 10:24**MOT test number** 344387003860**Result** ✓ Passed**MOT #6** 2016-03-16 14:08**MOT test number** 611475470621**Result** ✓ Passed**MOT #5** 2015-03-09 13:57**MOT test number** 985098765054**Result** ✓ Passed**MOT #4** 2014-03-05 11:39**MOT test number** 975804864078**Result** ✓ Passed



MOT #3	2013-03-13 13:46
MOT test number	169242573030
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2012-03-14 09:26
MOT test number	775064172078
Result	✓ Passed

MOT #1	2011-02-23 11:47
MOT test number	886024851082
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-21
Last registration	2022-04-22
Complete history	See info



Registration #1	2008-03-21	20 mi
Registration #2	2011-02-23	22.060 mi
Registration #3	2012-03-14	32.799 mi
Registration #4	2013-03-13	43.033 mi
Registration #5	2014-03-05	54.647 mi
Registration #6	2015-03-09	65.960 mi
Registration #7	2016-03-16	77.137 mi
Registration #8	2017-03-15	86.594 mi
Registration #9	2018-03-22	95.337 mi
Registration #10	2019-03-22	104.337 mi
Registration #11	2020-03-22	113.337 mi
Registration #12	2021-03-22	122.337 mi
Registration #13	2022-03-22	131.337 mi
Registration #14	2023-03-22	140.337 mi
Registration #15	2024-03-22	149.337 mi
Registration #16	2025-03-22	158.337 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1423 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	R18A12301445