



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 33 L1H1 100 SWB PV
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-16
Pictures	16
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	11
Total items failed	20

MOT #16	2023-10-05 09:35
MOT test number	246497766810
Result	✓ Passed
Next expiry date	2024-10-04

MOT #15	2023-09-27 16:23
MOT test number	282515333796
Result	✗ Failed
Fail	Nearside Front Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #14** 2023-09-02 13:50**MOT test number** 968349568925**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Shock absorbers has a serious fluid leak Both. (5.3.2 (b))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2022-09-19 12:21**MOT test number** 721949332161**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-01-12 16:43**MOT test number** 307768273445**Result** ✓ Passed**MOT #11** 2021-01-12 16:43**MOT test number** 505046741949**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #10** 2019-11-13 16:05**MOT test number** 195971067003**Result** ✓ Passed

**MOT #9** 2018-11-16 15:27**MOT test number** 697980171831**Result** ✓ Passed**Advice** Oil leak**MOT #8** 2017-09-21 11:32**MOT test number** 110095668774**Result** ✓ Passed**MOT #7** 2017-09-21 09:29**MOT test number** 589859325855**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2016-10-14 13:36**MOT test number** 885747165476**Result** ✓ Passed**Advice** Services brake just within limits

**MOT #5** 2016-10-13 10:22**MOT test number** 136439678812**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Advice** Services brake just within limits**Fail** Offside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)**MOT #4** 2015-09-16 12:45**MOT test number** 487264706172**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-09-16 16:08**MOT test number** 448119954229**Result** ✓ Passed**MOT #2** 2014-09-16 10:56**MOT test number** 608109654272**Result** ✗ Failed**Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Power steering pipe(s) or hose(s) leaking from a joint (2.3.3b)**Fail** Offside Rear Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)



MOT #1	2013-09-09 09:59
MOT test number	359952153466
Result	✓ Passed
Advice	Power steering pipe(s) or hose(s) has slight seepage from a seal (2.3.3b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
4 October 2024

Tax status		Valid until 1 July
Days left		62
MOT expiry date		4 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YB10ZJV
Plate since	2024-03-28
Current registration	YB10ZJV
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-08-24
Last registration	2023-10-05
Complete history	See info



Registration #1	2010-08-24	22 mi
Registration #2	2013-09-09	61.419 mi
Registration #3	2014-09-16	78.954 mi
Registration #4	2014-09-16	78.954 mi
Registration #5	2015-09-16	89.109 mi
Registration #6	2016-10-13	97.840 mi
Registration #7	2016-10-14	97.840 mi
Registration #8	2017-09-21	107.292 mi
Registration #9	2017-09-21	107.296 mi
Registration #10	2018-09-21	117.248 mi
Registration #11	2019-09-21	127.200 mi
Registration #12	2020-09-21	137.152 mi
Registration #13	2021-09-21	147.104 mi
Registration #14	2022-09-21	157.056 mi
Registration #15	2023-09-21	167.008 mi
Registration #16	2023-09-21	167.008 mi
Registration #17	2023-09-21	167.008 mi
Registration #18	2023-10-05	167.008 mi

More info >



Dimensions & weight

Width	2508 mm
Height	2254 mm
Length	4963 mm
Kerb weight	1845 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ10393196