



HYUNDAI



KVIOJXO


report date: 2024-03-29

## General information

Make	HYUNDAI
Model	MATRIX COMFORT
Colour	Blue
Year of manufacture	2010
Top speed	106 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	39.2 mpg
CO2 emission	171 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-07-14
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-14
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-14
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	4
Total items failed	4

MOT #16	2024-03-07 09:41
MOT test number	442459020062
Result	✓ Passed
Next expiry date	2025-03-14

MOT #15	2023-03-15 15:40
MOT test number	182122575074
Result	✓ Passed

MOT #14	2023-03-15 13:14
MOT test number	921763323444
Result	✗ Failed

**Fail** Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #13	2022-03-05 12:23
MOT test number	161192913636
Result	✓ Passed

**Advice** Front Tyre slightly damaged 2 x tyres inner edge wear (5.2.3 (d) (ii))

**MOT #12** 2022-03-05 12:23**MOT test number** 453676573435**Result** ✗ Failed**Advice** Front Tyre slightly damaged 2 x tyres inner edge wear (5.2.3 (d) (ii))**Pass with rectification** Offside Rear Stop lamp(s) not working customer provided bulb working (4.3.1 (a) (ii))**MOT #11** 2021-02-23 08:55**MOT test number** 449370470538**Result** ✓ Passed**MOT #10** 2020-02-25 08:42**MOT test number** 706903445864**Result** ✓ Passed**MOT #9** 2019-02-26 15:18**MOT test number** 126580177667**Result** ✓ Passed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #8** 2019-02-26 08:42**MOT test number** 697460966676**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #7** 2018-02-27 09:22**MOT test number** 425617999949**Result** ✓ Passed



MOT #6	2017-02-21 09:05
--------	------------------

MOT test number	946637805172
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2016-02-23 10:28
--------	------------------

MOT test number	145798693897
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #4	2016-02-23 08:52
--------	------------------

MOT test number	796885537413
-----------------	--------------

Result	✗ Failed
--------	----------

**Fail** Nearside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #3	2015-02-24 09:03
--------	------------------

MOT test number	379655555011
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2014-02-25 09:39
--------	------------------

MOT test number	435946954021
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #1	2013-02-26 10:33
--------	------------------

MOT test number	909087353044
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
14 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	14 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>KV10JXO</b>
Plate since	2024-03-29
Current registration	<b>KV10JXO</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-01
Last registration	2024-03-07
Complete history	<a href="#">See info</a>



Registration #1	2010-03-01	15 mi
Registration #2	2013-02-26	15.155 mi
Registration #3	2014-02-25	18.281 mi
Registration #4	2015-02-24	21.254 mi
Registration #5	2016-02-23	25.640 mi
Registration #6	2016-02-23	25.640 mi
Registration #7	2017-02-21	29.306 mi
Registration #8	2018-02-27	32.622 mi
Registration #9	2019-02-26	35.106 mi
Registration #10	2019-02-26	35.107 mi
Registration #11	2019-02-26	35.107 mi
Registration #12	2019-02-26	35.107 mi
Registration #13	2019-02-26	35.107 mi
Registration #14	2019-02-26	35.107 mi
Registration #15	2019-02-26	35.107 mi
Registration #16	2019-02-26	35.107 mi
Registration #17	2019-02-26	35.107 mi
Registration #18	2019-02-26	35.107 mi
Registration #19	2019-02-26	35.107 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1635 mm
Length	4060 mm
Wheel base	2600 mm
Kerb weight	1327 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED9W173238