



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D3 ES
Colour	Silver
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-04-29
Pictures	31
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-19
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	17
Total items failed	4
MOT #14	2024-03-11 13:09
MOT test number	169777313882
Result	✓ Passed
Next expiry date	2025-03-19
MOT #13	2023-03-20 14:25
MOT test number	394605283512
Result	✓ Passed
MOT #12	2022-04-24 07:30
MOT test number	774688656377
Result	✓ Passed
MOT #11	2021-07-26 11:24
MOT test number	348671400081
Result	✓ Passed

**MOT #10** 2020-08-06 12:13**MOT test number** 856413995110**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2019-08-08 15:54**MOT test number** 836088385227**Result** ✓ Passed**Advice** Front brake pads wearing half way**MOT #8** 2019-08-07 14:47**MOT test number** 580087931337**Result** ✗ Failed**Advice** Front brake pads wearing half way**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #7** 2018-08-09 14:21**MOT test number** 122750290907**Result** ✓ Passed**Advice** Near side rear tyre wearing close to wear indicator**Advice** Front brake pads wearing low

**MOT #6** 2017-07-31 14:53**MOT test number** 684224049601**Result** ✓ Passed**Advice** Child seat fitted not allowing full inspection of adult bet n/s/r**MOT #5** 2017-07-31 14:53**MOT test number** 798088659378**Result** ✗ Failed**Advice** Child seat fitted not allowing full inspection of adult bet n/s/r**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2016-08-12 13:45**MOT test number** 698441927260**Result** ✓ Passed**Advice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2015-08-13 10:55**MOT test number** 306104937030**Result** ✓ Passed**MOT #2** 2014-08-12 16:23**MOT test number** 435864724232**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1	2014-08-12 16:23
MOT test number	188694824260
Result	✗ Failed
Notice	Child seat fitted not allowing full inspection of adult belt
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Notice	Engine covers fitted obscuring some components in the engine bay
Pass with rectification	Nearside Front Headlamp aim too low (1.8)
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
19 March 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-14
Last registration	2024-03-11
Complete history	See info



Registration #1	2011-09-14	6 mi
Registration #2	2014-08-12	35.516 mi
Registration #3	2015-08-13	42.634 mi
Registration #4	2016-08-12	46.224 mi
Registration #5	2017-07-31	49.289 mi
Registration #6	2017-07-31	49.289 mi
Registration #7	2018-08-09	55.214 mi
Registration #8	2019-08-07	60.272 mi
Registration #9	2020-05-20	65.330 mi
Registration #10	2021-05-20	70.388 mi
Registration #11	2022-05-20	75.446 mi
Registration #12	2023-05-20	80.504 mi
Registration #13	2024-03-11	85.562 mi
Registration #14	2024-03-11	85.562 mi
Registration #15	2024-03-11	85.562 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1504 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1012435