





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|-----------------------|
| Model | TIGUAN SE NAV TDI BMT |
| Colour | Red |
| Year of manufacture | 2018 |
| Top speed | 127 mph |
| 0 - 100 km/h | 9.3 seconds |
| 0 - 60 mph | 9.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 110 kW / 150 HP / 148 BHP |
|-------------------------|---------------------------|
| Max. torque | 340 Nm at 1.750 rpm |
| Engine capacity | 1.968 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 125 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



Internet history

Entry 1


Date 2021-08-10

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2025-03-25 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 7 |
| Total items failed | 2 |

| MOT #5 | 2024-03-26 10:40 |
|------------------|------------------|
| MOT test number | 727874847235 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-25 |

| MO1 #4 | 2023-1 | 00-22 12.49 |
|----------|---|---------------|
| MOT test | t number 779 | 619140815 |
| Result | | ✓ Passed |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |
| Advice | Brake disc worn, pitted or scored, but not seriously weakened both rear outer faces (1.1 | .14 (a) (ii)) |
| Advice | Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice | Brake disc worn, pitted or scored, but not seriously weakened both front inner faces (1.1 | 14 (a) |
| Advice | Tyre slightly damaged/cracking or perishing all four outer sidewalls cracking (5.2.3 (d) (i | i)) |

| MOT #3 | | 2022-07-07 10:25 |
|----------|--|------------------|
| MOT test | number | 338951850895 |
| Result | | ✓ Passed |
| Advice | Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt | |

CarCheck.co.uk page 3/11



MOT #2 2021-05-07 12:53 **MOT test number** 432709481936 Result ✓ Passed **MOT #1** 2021-05-07 12:53 **MOT test number** 714420787567 Result × Failed **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 306 |
| MOT expiry date | 25 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| - | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



| Owner history | |
|--|---|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. | |
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | NIE |
| Plate since | |
| Current registration | AIR AIR |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-06-27 |
| Last registration | 2024-03-26 |
| Complete history | See info |



| Registration #1 | 2018-06-27 | 7 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-05-07 | 10.125 mi |
| Registration #3 | 2021-05-07 | 10.125 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 ea |
| Registration #7 | | 11,177 ms |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 96% |
| Children | 84% |
| Pedestrian | 72% |
| Safety systems | 68% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 2099 mm |
|---------------------|---------|
| Height | 1632 mm |
| Length | 4486 mm |
| Wheel base | 2681 mm |
| Kerb weight | 1568 kg |
| Max. allowed weight | 2150 kg |

Additional information

| Fuel tank capacity | 58 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| CarChack co.uk | page 11/11 |

CarCheck.co.uk page 11/11

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | DFGA845412 |