



SW640DG

report date: 2024-03-28

General information

Make	FIAT
Model	PANDA EASY
Colour	White
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-10-03
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-12-01
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	20
Total items failed	4

MOT #8	2023-11-03 11:19
MOT test number	391587317123
Result	✓ Passed
Next expiry date	2024-12-01
Advice	Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
Advice	Front Shock absorbers has light misting of oil both sides (5.3.2 (b))

MOT #7	2022-11-18 10:45
MOT test number	694304229072
Result	✓ Passed

MOT #6	2021-12-02 13:04
MOT test number	747570061861
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5	2020-11-20 16:00
MOT test number	724095867831
Result	✓ Passed
Advice	Oil leak, but not excessive sump (8.4.1 (a) (i))

**MOT #4**

2020-11-19 15:04

**MOT test number**

700737476867

**Result**

✗ Failed

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Shock absorbers has an excessively worn bush top bush (5.3.2 (c))
- Fail** Exhaust emissions likely to be affected by an exhaust leak front flexy detached (8.2.1.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Underside components corroded
- Advice** Oil leak, but not excessive sump pan porous (8.4.1 (a) (i))
- Advice** Tyre slightly damaged/cracking or perishing both rear cracked on tread (5.2.3 (d) (ii))
- Fail** Offside Rear Shock absorbers has an excessively worn bush top bush (5.3.2 (c))

**MOT #3**

2019-11-20 12:06

**MOT test number**

258259979536

**Result**

✓ Passed

- Minor** Offside Rear fog lamp lens defective which has no effect on emitted light damaged/water ingress (4.5.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #2**

2018-12-01 11:22

**MOT test number**

780819446085

**Result**

✓ Passed



MOT #1 2017-12-18 09:36

MOT test number 838946301411

Result ✓ Passed

- Advice** Rear fog lamp damaged, but still visible from a reasonable distance (1.3.2d)
- Advice** Items removed from driver's view prior to test
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
1 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	1 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-01-09
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2015-01-09	14 mi
Registration #2	2017-12-18	37.024 mi
Registration #3	2018-12-01	46.307 mi
Registration #4	2019-11-20	54.115 mi
Registration #5	2020-11-19	65.320 mi
Registration #6	2021-11-18	76.525 mi
Registration #7	2022-11-17	87.730 mi
Registration #8	2023-11-03	98.935 mi
Registration #9	2023-11-03	110.140 mi
Registration #10	2023-11-03	121.345 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1410265