



report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-05
Pictures	44
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-10-21
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	28
Total items failed	17

MOT #21	2022-10-22 13:37
---------	------------------

MOT test number	528713565750
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-10-21
------------------	------------

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge worn on edges - both tyres (5.2.3 (e))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Coil spring corroded all coil springs (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both brake discs (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #20**

2022-10-22 13:37

MOT test number

843075410170

Result**✗ Failed****Advice** Coil spring corroded all coil springs (5.3.1 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge worn on edges - both tyres (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both brake discs (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))**MOT #19**

2021-10-20 09:44

MOT test number

365397989193

Result**✓ Passed****MOT #18**

2021-10-19 14:35

MOT test number

323906926684

Result**✗ Failed****Fail** Exhaust has a major leak of exhaust gases front flexi. (6.1.2 (a))

**MOT #17** 2020-11-16 10:24**MOT test number** 520589832725**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #16** 2019-11-18 11:49**MOT test number** 994320112502**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2019-11-18 09:03**MOT test number** 771739631509**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MOT #14** 2018-11-19 15:43**MOT test number** 167946864403**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2018-11-19 11:01**MOT test number** 782604087682**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #12** 2017-11-17 15:04**MOT test number** 279153700329**Result** ✓ Passed**MOT #11** 2017-11-17 10:07**MOT test number** 541625811597**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #10** 2016-11-21 16:09**MOT test number** 147386944372**Result** ✓ Passed

**MOT #9** 2016-11-21 14:47**MOT test number** 965659998347**Result** ✗ Failed

- Fail** Offside Front Headlamp insecure (1.7.3)
- Fail** Offside Front Headlamp aim too low (1.8)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

MOT #8 2016-02-25 15:47**MOT test number** 140503843824**Result** ✓ Passed**MOT #7** 2016-02-25 13:44**MOT test number** 502736165843**Result** ✗ Failed

- Fail** Nearside Front coil spring broken (2.4.C.1a)

MOT #6 2015-02-19 14:04**MOT test number** 505450855054**Result** ✓ Passed**MOT #5** 2015-02-19 09:53**MOT test number** 708500455013**Result** ✗ Failed

- Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**MOT #4** 2014-03-05 12:35**MOT test number** 489014564076**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-02-21 15:32**MOT test number** 149812153415**Result** ✓ Passed**MOT #2** 2013-02-21 15:32**MOT test number** 108852553496**Result** ✗ Failed**Pass with rectification** Offside Upper Rear position lamp(s) not working (1.1.A.3b)**MOT #1** 2012-02-24 14:46**MOT test number** 365485752094**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-03-30
Last registration	2022-10-22
Complete history	See info



Registration #1	2009-03-30	28 mi
Registration #2	2012-02-24	41.671 mi
Registration #3	2013-02-21	59.840 mi
Registration #4	2014-03-05	74.578 mi
Registration #5	2015-02-19	96.270 mi
Registration #6	2015-02-19	96.270 mi
Registration #7	2016-02-25	114.109 mi
Registration #8	2016-02-25	114.109 mi
Registration #9	2016-11-21	124.504 mi
Registration #10	2016-11-21	124.504 mi
Registration #11	2017-11-17	139.328 mi
Registration #12	2018-05-22	151.277 mi
Registration #13	2018-05-22	151.277 mi
Registration #14	2018-05-22	151.277 mi
Registration #15	2018-05-22	151.277 mi
Registration #16	2018-05-22	151.277 mi
Registration #17	2018-05-22	151.277 mi
Registration #18	2018-05-22	151.277 mi
Registration #19	2018-05-22	151.277 mi
Registration #20	2018-05-22	151.277 mi
Registration #21	2018-05-22	151.277 mi
Registration #22	2022-10-22	151.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694