



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Red
Year of manufacture	2007
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	215 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-15
Pictures	26
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-22
MOT pass rate	94 %
MOT passed	16
Failed MOT tests	1
Total advice items	35
Total items failed	1

MOT #17	2023-07-24 10:08
MOT test number	525673200204
Result	✓ Passed
Next expiry date	2024-08-22

MOT #16	2022-08-02 12:02
MOT test number	150477476793
Result	✓ Passed

MOT #15	2021-08-23 15:20
MOT test number	710078201932
Result	✓ Passed

MOT #14	2021-01-26 12:50
MOT test number	685436932552
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on edges still just legal (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges still just legal (5.2.3 (e))

MOT #13	2020-01-22 13:45
MOT test number	215202838652
Result	✓ Passed

**MOT #12** 2019-02-20 10:40**MOT test number** 187284997577**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play slight play (5.3.4 (a) (i))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides cracks in bushes (5.3.4 (a) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #11** 2019-02-20 10:09**MOT test number** 732545556992**Result** ✓ Passed**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #10** 2018-02-15 14:42**MOT test number** 738521036793**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s) very slight**MOT #9** 2017-03-14 13:02**MOT test number** 507870880278**Result** ✓ Passed**MOT #8** 2016-10-11 11:43**MOT test number** 590737011089**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Engine covers fitted**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #7**

2015-11-03 14:54

MOT test number

681763348235

Result

✓ Passed

- Advice** Engine cover + under panels fitted
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Castor bush separating from casing (2.4.G.2)
- Advice** Stone chips to front windscreen
- Advice** Front Inner Brake pad(s) wearing thin Both (3.5.1g)
- Advice** O/s/r tyre scrubbing out on inner edge
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Castor (2.4.G.2)

MOT #6

2015-10-27 17:19

MOT test number

315642783076

Result

✗ Failed

- Fail** Nearside Front suspension has excessive play in a upper suspension ball joint (2.5.B.1a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Castor bush separating from casing (2.4.G.2)
- Advice** O/s/r tyre scrubbing out on inner edge
- Advice** Front Inner Brake pad(s) wearing thin Both (3.5.1g)
- Advice** Engine cover + under panels fitted
- Advice** Offside Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Castor (2.4.G.2)
- Advice** Stone chips to front windscreen
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #5** 2014-10-21 12:04**MOT test number** 629974594276**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** N/s/r tyre scrubbing inner edge.**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2013-10-21 11:37**MOT test number** 286104693298**Result** ✓ Passed**Notice** Both rear tyres wearing thin on edges**Notice** O/s/f tyre scrubbed out on edges**MOT #3** 2012-10-30 10:11**MOT test number** 148074802356**Result** ✓ Passed**MOT #2** 2011-11-07 09:21**MOT test number** 539081911319**Result** ✓ Passed**Notice** Rear tyres wearing thin.**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Notice** Some cracking on inner walls of front tyres.



MOT #1	2010-12-09 14:19
MOT test number	652663940366
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
16 March 2024

✓

MOT

Expires:
22 August 2024

Tax status	Expired at 16 March 2024
Days left	45 days too late
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 
Plate since	2019-06-29
Current registration	 
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-14
Last registration	2023-07-24
Complete history	See info



Registration #1	2007-12-14	8 mi
Registration #2	2010-12-09	18.904 mi
Registration #3	2011-11-07	30.500 mi
Registration #4	2012-10-30	37.552 mi
Registration #5	2013-10-21	44.063 mi
Registration #6	2014-10-21	50.376 mi
Registration #7	2015-10-27	56.579 mi
Registration #8	2015-11-03	56.669 mi
Registration #9	2016-10-11	61.103 mi
Registration #10	2017-03-14	62.905 mi
Registration #11	2018-03-20	65.377 mi
Registration #12	2019-03-20	65.377 mi
Registration #13	2020-03-20	65.377 mi
Registration #14	2021-03-20	65.377 mi
Registration #15	2022-03-20	65.377 mi
Registration #16	2023-03-20	65.377 mi
Registration #17	2024-03-20	65.377 mi
Registration #18	2025-03-20	65.377 mi
Registration #19	2026-03-20	65.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040385213