





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI SE NAV BLUE DRIVE
Colour	Silver
Year of manufacture	2017
Top speed	119 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	280 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



EX67YFT

report date: 2024-03-28

Internet history


Entry 1

Date 2021-09-21

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-03
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #5	2023-08-09 12:57
MOT test number	750747569642
Result	✓ Passed
Next expiry date	2024-09-03
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (a) (ii))	d both sides inner faces (1.1.14

MOT #4	2022-08-18 13:08
MOT test number	497506719820
Result	✓ Passed
MOT #3	2021-08-19 08:39
MOT test number	560909590014
Result	✓ Passed

Result		✓ Passed
MOT #2	2020-	09-01 14:42
MOT test	number 667	7419087523
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii)))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	
Advice	Rear Tyre slightly damaged/cracking or perishing both - cracking on tread (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



MOT #1 2020-09-01 12:21

MOT test number 696122379791

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Advice Rear Tyre slightly damaged/cracking or perishing both - cracking on tread (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Fail Front Windscreen wiper does not clear the windscreen effectively both - torn (3.4 (b) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	3 September 2024
Full MOT history	See MOT history

Tax calculation

1 10 10 10 1	
Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-04
Last registration	2023-08-09
Complete history	See info



Registration #1	2017-09-04	21 mi
Registration #2	2020-09-01	31.929 mi
Registration #3	2020-09-01	31.929 mi
Registration #4	2021-08-19	41.212 mi
Registration #5		11.177 mi
Registration #6		11.777 44
Registration #7		11.777 no

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4745 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2090 kg

Additional information

		•
Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number D4FDHU730401