



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D5 SE V50
Colour	Grey
Year of manufacture	2008
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-12
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-26
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	14
Total items failed	11

MOT #19	2024-01-05 17:25
MOT test number	486427256163
Result	✓ Passed
Next expiry date	2025-01-26

MOT #18	2023-01-27 17:37
MOT test number	189343730134
Result	✓ Passed

MOT #17	2023-01-27 12:35
MOT test number	781493316705
Result	✗ Failed
<div><div>Fail</div> Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</div> <div><div>Fail</div> Front Position lamp not working N/S &amp; O/S (4.2.1 (a) (ii))</div>	

MOT #16	2022-01-04 11:51
MOT test number	673110902856
Result	✓ Passed

**MOT #15** 2021-01-08 16:59**MOT test number** 391981221471**Result** ✓ Passed**Advice** Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))**MOT #14** 2020-12-18 10:32**MOT test number** 549927668075**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush front wish bone (5.3.4 (a) (i))**Fail** Nearside Front Tyre has ply or cords damaged tyre out of shape 2m/m (5.2.3 (d) (ii))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**MOT #13** 2019-06-21 12:07**MOT test number** 631296880498**Result** ✓ Passed**MOT #12** 2018-06-22 14:12**MOT test number** 965302714368**Result** ✓ Passed**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #11** 2018-06-22 10:33**MOT test number** 427321179330**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Nail in tyre**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #10** 2017-05-15 12:43**MOT test number** 707720939268**Result** ✓ Passed**MOT #9** 2016-03-16 12:15**MOT test number** 179723984589**Result** ✓ Passed**MOT #8** 2016-03-16 12:15**MOT test number** 694266285448**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2015-04-14 14:18**MOT test number** 726164905176**Result** ✓ Passed

**MOT #6** 2015-04-13 10:34**MOT test number** 938603605125**Result** ✗ Failed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #5** 2014-03-27 10:29**MOT test number** 537756984073**Result** ✓ Passed**MOT #4** 2013-03-25 10:16**MOT test number** 447864683091**Result** ✓ Passed**MOT #3** 2012-03-27 10:14**MOT test number** 266477082026**Result** ✓ Passed**Notice** Rear brake pads worn low**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Notice** Nearside rear tyre worn very unevenly and tread "feathered"**Notice** Hand brake requires adjustment**Notice** Front brake pads worn very low**Notice** Nearside rear inner wheel rim distorted and damaged.**MOT #2** 2011-03-31 12:59**MOT test number** 535280491074**Result** ✓ Passed



MOT #1	2011-03-31 11:00
MOT test number	718110091082
Result	<div>✖ Failed</div>
<div><div>Fail</div>Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
26 January 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	26 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-02-20
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2008-02-20	9 mi
Registration #2	2011-03-31	45.792 mi
Registration #3	2011-03-31	45.792 mi
Registration #4	2012-03-27	58.655 mi
Registration #5	2013-03-25	69.302 mi
Registration #6	2014-03-27	81.037 mi
Registration #7	2015-04-13	91.916 mi
Registration #8	2015-04-14	91.919 mi
Registration #9	2016-03-16	100.060 mi
Registration #10	2016-03-16	100.060 mi
Registration #11	2017-05-15	105.228 mi
Registration #12	2018-05-20	110.397 mi
Registration #13	2019-05-20	115.566 mi
Registration #14	2020-05-20	120.735 mi
Registration #15	2021-05-20	125.904 mi
Registration #16	2022-05-20	131.073 mi
Registration #17	2023-05-20	136.242 mi
Registration #18	2024-01-05	141.411 mi
Registration #19	2024-01-05	141.411 mi
Registration #20	2024-01-05	141.411 mi
Registration #21	2024-01-05	141.411 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1568 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

620071