





General information

Make	VOLKSWAGEN
Model	EOS FSI
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	200 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg



MOT history MOT #15 2021-01-20 11:52 MOT test number 982562987413

Result	✓ Passed
Next expiry date	2022-01-19

MOT #14	2019-12-03 13:04
MOT test number	531777495381
Result	✓ Passed

MOT #13		2019-12-03 12:13
MOT test	number	278537531618
Result		🗙 Failed
MAJOR	Offside Front Headlamp aim too low (4.1.2 (a))	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #12	2018-	12-12 16:24
MOT test	number 44	4179578643
Result		🗸 Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)))))

MOT #11	2018-12-12 12:09	
MOT test number	756957953945	
Result	🗙 Failed	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
MAJOR Offside Headlamp aim too low (4.1.2 (a))		





MOT #10	2017-12-06 11:44
MOT test number	328737554273
Result	✓ Passed
МОТ #9	2016-12-15 16:16
MOT test number	292883348344
Result	✓ Passed
MOT #8	2016-01-23 16:38

MOT test	number	766233608139
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #7	2016-	01-23 16:38
MOT test number	69	8258538631
Result		🗙 Failed
Pass with rectification	Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)		
Advice Front Brake pad(s) wearing thin (3.5.1g)		
Pass with rectificationOffside Front position lamp(s) not working (1.1.A.3b)		





MOT #6		2015-01-02 15:11
MOT test	number	556562505001
Result		✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Notice	Under-trays fitted obscuring some underside components	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2014-01-03 09:48
MOT test number	947173504015
Result	✓ Passed

MOT #4	2012-12-03 08:44
MOT test number	838778732386
Result	✓ Passed
МОТ #3	2011-12-02 11:20
MOT test number	578396831347
Result	✓ Passed
МОТ #2	2010-11-29 11:05
MOT test number	482223630406
Result	✓ Passed

MOT #1	2009-12-11 11:58
MOT test number	231605249336
Result	✓ Passed





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETTOR
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-11-04
Last registration	2021-01-20
Complete history	See info



Registration #1	2006-11-04	18 mi
Registration #2	2009-12-11	18.478 mi
Registration #3	2010-11-29	21.724 mi
Registration #4	2011-12-02	27.081 mi
Registration #5	2012-12-03	30.714 mi
Registration #6	2014-01-03	33.682 mi
Registration #7	2015-01-02	51.660 mi
Registration #8	2016-01-23	66.088 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1791 mm Height 1437 mm Length 4407 mm Wheel base 2578 mm Kerb weight 1481 kg Max. allowed weight 1950 kg Additional information Fuel tank capacity 55 I **Fuel delivery Direct Injection** Number of doors 2

CarCheck.co.uk

Number of seats	4
Engine number	BVY 084246