





General information

Make PEU	IGEOT
Model 307	S
Colour Blue	2
Year of manufacture 200	6
Top speed 107	mph
0 - 60 mph 12.8	3 seconds
Gearbox 5 sp	beed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	133 Nm at 3.250 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	155 g/km
CO2 label	G







Internet history

Entry 2

Date Pictures 2021-07-10

18

Listing price

WINNER


View report



source: cargurus.co.uk

CERTIFICATE of

Entry 1	
Date	2021-07-08
Pictures	17
Listing price	View report



source: autotrader.co.uk









MOT history

MOT expiry date	2025-01-16
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	40
Total items failed	7

MOT #23		2024-01-17 09:46
MOT test	number	601134867370
Result		🗸 Passed
Next expi	ry date	2025-01-16
Advice	Play in steering rack inner joint(s) both	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Coolant leak	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #22		2023-01-13 10:49
MOT test	number	515714469435
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #21		2022-01-17 08:58
MOT test number		651937186448
Result		✓ Passed
Advice Front Brake disc	worn, pitted or scored, but not seriously	y weakened (1.1.14 (a) (ii))
Advice Rear Brake disc	worn, pitted or scored, but not seriously	v weakened (1.1.14 (a) (ii))
Advice Oil leak, but not	excessive (8.4.1 (a) (i))	

MOT #20		2022-01-14 13:50
MOT test i	number	311498324812
Result		🗙 Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Pass wit	h rectification Nearside Headlamp not working on dipped beam (4.1.1 (a)	(ii))
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
DANGER	OUS Parking brake efficiency less than 50% of the required value (1.4.2 (a)) (ii))
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))	





MOT #19		2021-02-13 11:04
MOT test	number	515632643748
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	

MOT #18		2020-02-17 11:06
MOT test	number	248220486242
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Play in steering rack inner joint(s)	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #17	2019-02-18 14:27
MOT test number	255961184775
Result	✓ Passed
Advice Play in steering rack inner joint(s)	





MOT #16		2019-02-15 15:13
MOT test i	number	544802091360
Result		🗙 Failed
MAJOR	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Play in steering rack inner joint(s)	
MAJOR	Exhaust has a major leak of exhaust gases front pipe (6.1.2 (a))	

MOT #15	2018-02-17 11:08
MOT test number	988574100640
Result	✓ Passed

MOT #14	2018-02-17 11:08
MOT test number	481819548903
Result	× Failed
Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)
Pass with rectification	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #13	2017-02-06 09:10
MOT test number	246515430983
Result	✓ Passed

MOT #12		2017-02-06 09:10
MOT test number		745507213992
Result		🗙 Failed
Pass with rectification	Offside Rear Rear position lamp(s) not working (1.1.A.3b)	

MOT #11	2016-02-09 12:35
MOT test number	367434866153
Result	✓ Passed





MOT #10		
	2015-10-15 09:57	
MOT test number	335495608847	
Result	✓ Passed	
MOT #9	2015-10-15 09:57	
MOT test number	622959403895	
Result	× Failed	
Pass with rectification	Windscreen wiper does not clear the windscreen effectively both (8.2.2)	
MOT #8	2014-10-17 09:24	
MOT test number	355810894434	
Result	✓ Passed	
MOT #7	2013-10-09 09:53	
MOT test number	906482583238	
Result	✓ Passed	
Notice Play in steering rack inner joint(s)		
МОТ #6	2012-10-03 15:23	
MOT test number	358017472445	
Result	✓ Passed	
MOT #5	2011-10-20 15:11	
MOT test number	355143191244	

🗸 Passed





MOT #4	2011-10-20 11:36
MOT test number	316593891465
Result	🗙 Failed
Notice Osr brake disc pitted.	
Advice Nearside Front Ball joint has slight play (2.2.B.1f)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Oil leak	
Fail Offside Rear Mechanical brake component has restricted free movement (3.5.1k)	
Notice Nsf tyre on 3mm.	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2010-10-27 16:05
MOT test number	913980900371
Result	✓ Passed

MOT #2		2010-10-27 16:05
MOT test number		450120600370
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)	

MOT #1	2009-10-29 12:16
MOT test number	221322409311
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 July 2024	✓ MOT Expires: 16 January 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lange
Туре	
Damage 2	AMPL
	F Stores
Date	Nº I
Category	ante
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-10-30
Last registration	2024-01-17
Complete history	See info



2006-10-30	27 mi
2009-10-29	28.459 mi
2010-10-27	35.190 mi
2011-10-20	45.011 mi
2011-10-20	45.011 mi
2012-10-03	55.247 mi
2013-10-09	61.320 mi
2014-10-17	62.898 mi
2015-10-15	64.638 mi
2015-10-15	64.638 mi
2010 02 00	CE 222
2016-02-09	65.223 mi
2017-02-06	65.223 mi 70.847 mi
2017-02-06	70.847 mi
2017-02-06 2017-02-06	70.847 mi 70.847 mi
2017-02-06 2017-02-06	70.847 mi 70.847 mi
2017-02-06 2017-02-06	70.847 mi 70.847 mi
2017-02-06 2017-02-06	70.847 mi 70.847 mi
2017-02-06 2017-02-06	70.847 mi 70.847 mi
2017-02-06	70.847 mi 70.847 mi
	2009-10-29 2010-10-27 2011-10-20 2011-10-20 2012-10-03 2013-10-09 2014-10-17 2015-10-15





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1757 mm
Height	1530 mm
Length	4211 mm
Wheel base	2608 mm
Kerb weight	1249 kg
Max. allowed weight	1650 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles	2
Engine number	FE030215387