



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 LX HDI (90BHP)
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-11
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #28	2021-09-11 08:52
MOT test number	226284387208
Result	✓ Passed
Next expiry date	2022-10-01
Advice	Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

MOT #27	2021-09-11 08:52
MOT test number	811340677777
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #26	2020-09-30 16:40
MOT test number	497008157692
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged distorted on tread face inner edge (5.2.3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Nail in tyre
Advice	Parking brake release button damaged
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Non obligatory mirror damaged

**MOT #25**

2020-09-30 10:18

MOT test number

541380959172

Result**✗ Failed**

- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Tyre slightly damaged distorted on tread face inner edge (5.2.3 (d) (ii))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Non obligatory mirror damaged
- Advice** Parking brake release button damaged
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #24

2019-10-01 11:53

MOT test number

974400492939

Result**✓ Passed**

- Advice** Nearside Non obligatory mirror damaged
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Parking brake release button damaged
- Advice** Offside Rear Tyre slightly damaged Slightly distorted on tread face inner edge (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged Slightly distorted on tread face inner edge (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #23**

2019-10-01 08:39

MOT test number

121369203281

Result**✗ Failed****Advice** Nearside Rear Tyre slightly damaged Slightly distorted on tread face inner edge (5.2.3 (d) (ii))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Non obligatory mirror damaged**Advice** Offside Rear Tyre slightly damaged Slightly distorted on tread face inner edge (5.2.3 (d) (ii))**Advice** Parking brake release button damaged**Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**MOT #22**

2018-10-01 16:15

MOT test number

160330855681

Result**✓ Passed****Advice** Parking brake release button damaged**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Non obligatory mirror damaged

**MOT #21**

2018-10-01 08:56

MOT test number

321376785121

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Non obligatory mirror damaged
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front bumper lower trim insecure
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))
- Advice** Parking brake release button damaged

MOT #20

2017-09-08 16:23

MOT test number

709256969285

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Handbrake release button damaged
- Advice** Nearside Non obligatory mirror damaged

**MOT #19** 2017-09-08 12:14**MOT test number** 954926903609**Result** ✗ Failed**Fail** Central Rear Stop lamp has less than 50% of the light sources illuminating (1.2.1b)**Fail** Nearside Front Stop lamp not working (1.2.1b)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #18** 2016-09-22 15:17**MOT test number** 312470888926**Result** ✓ Passed**Advice** Handbrake release button damaged**Advice** Nearside Non obligatory mirror damaged**MOT #17** 2016-09-22 09:51**MOT test number** 201168135003**Result** ✗ Failed**Advice** Handbrake release button damaged**Advice** Nearside Non obligatory mirror damaged**Advice** Horn not working, intermittent**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #16** 2015-10-02 12:05**MOT test number** 896197066480**Result** ✓ Passed

**MOT #15**

2015-10-01 12:03

MOT test number

149570235064

Result**✗ Failed****Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #14**

2014-10-31 15:12

MOT test number

757784504308

Result**✓ Passed****Notice** N/s/f headlamp bracket broken**Notice** Engine management light on**Notice** Very slight movement in o/s/f steering rack**MOT #13**

2014-10-30 13:46

MOT test number

909543104391

Result**✗ Failed****Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Very slight movement in o/s/f steering rack**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** N/s/f headlamp bracket broken**Notice** Engine management light on

**MOT #12**

2013-11-04 11:18

MOT test number

509528303308

Result

✓ Passed

- Notice** Handbrake release button missing
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Horn not working interminnantly
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11

2012-10-15 17:48

MOT test number

149469282281

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Horn int inop
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front wheel arch liner insecure
- Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
- Notice** E.M.L light on
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Handbrake lever button missing
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #10

2012-10-15 14:53

MOT test number

398949982203

Result		✗ Failed
Fail	Nearside Rear position lamp(s) not working (1.1.A.3b)	
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Horn int inop	
Fail	Offside Headlamp not working on dipped beam (1.7.5a)	
Notice	Nearside front wheel arch liner insecure	
Fail	Offside Stop lamp not working (1.2.1b)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	E.M.L light on	
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)	
Advice	Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)	
Notice	Handbrake lever button missing	



MOT #9

2011-11-09 11:20

MOT test number

437943311395

Result

✓ Passed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice

Nearside front wheel arch liner little insecure

Notice

Both rear tyre slight side wall damage

Notice

Horn int inop

Notice

Brake pedel rubber slight insecure

Notice

Nearside front tyre slight sidewall damage

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice

Slight play in steering rack o/s

Notice

Headlamp switch sticking int

Notice

Nearside headlamp broken slightly insecure



MOT #8	2011-11-08 11:49
MOT test number	585552811381
Result	✗ Failed
Notice	Nearside front wheel arch liner little insecure
Notice	Both rear tyre slight side wall damage
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Notice	Brake pedel rubber slight insecure
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside headlamp broken slightly insecure
Notice	Slight play in steering rack o/s
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Notice	Headlamp switch sticking int
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Horn int inop
Notice	Nearside front tyre slight sidewall damage

MOT #7	2010-11-04 12:39
MOT test number	571948500319
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2009-10-17 12:32
MOT test number	261150099276
Result	✓ Passed



MOT #5	2009-10-17 12:32
MOT test number	243820199237
Result	✗ Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)

MOT #4	2008-10-06 16:33
MOT test number	430590888272
Result	✓ Passed

MOT #3	2007-09-27 14:40
MOT test number	684560177260
Result	✓ Passed

MOT #2	2006-08-11 11:32
MOT test number	374643526262
Result	✓ Passed

MOT #1	2005-09-27 09:41
MOT test number	511390975268
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2002-09-26
Last registration	2021-09-11
Complete history	See info



Registration #1	2002-09-26	28 mi
Registration #2	2005-09-27	21.181 mi
Registration #3	2006-08-11	24.913 mi
Registration #4	2007-09-27	29.566 mi
Registration #5	2008-10-06	34.754 mi
Registration #6	2009-10-17	40.053 mi
Registration #7	2010-11-04	43.087 mi
Registration #8	2011-11-08	46.084 mi
Registration #9	2011-11-09	46.084 mi
Registration #10	2012-10-15	49.942 mi
Registration #11	2012-10-15	49.942 mi
Registration #12	2013-11-04	54.235 mi
Registration #13	2014-10-30	57.695 mi
Registration #14	2014-10-31	57.695 mi
Registration #15	2015-10-01	61.642 mi
Registration #16	2016-09-29	65.597 mi
Registration #17	2016-09-29	65.597 mi
Registration #18	2016-09-29	65.597 mi
Registration #19	2016-09-29	65.597 mi
Registration #20	2016-09-29	65.597 mi
Registration #21	2016-09-29	65.597 mi
Registration #22	2016-09-29	65.597 mi
Registration #23	2016-09-29	65.597 mi
Registration #24	2016-09-29	65.597 mi
Registration #25	2016-09-29	65.597 mi
Registration #26	2016-09-29	65.597 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	DYLH3059628