




report date: 2024-03-29

General information

Make	CITROEN
Model	C4 PURETECH FLAIR S/S
Colour	Silver
Year of manufacture	2016
Top speed	117 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	100 g/km
CO2 label	A





Internet history

Entry 3

Date	2022-05-28
Pictures	43
Listing price	View report



source: cargurus.co.uk

Entry 2

Date	2021-08-02
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-01
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	3

MOT #7	2023-08-25 14:19
MOT test number	804087587218
Result	✓ Passed
Next expiry date	2024-08-24

MOT #6	2022-08-03 14:43
MOT test number	553839838143
Result	✓ Passed

MOT #5	2021-08-13 08:09
MOT test number	820120289080
Result	✓ Passed

MOT #4	2021-08-06 07:44
MOT test number	685311367268
Result	✓ Passed

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))



MOT #3	2021-01-25 10:15
MOT test number	132832267671
Result	✓ Passed
Advice	Offside rear tyre 3.5mm tread & cracked & perished.
Advice	Vehicle front under tray damage & loose.
Advice	Nearside rear tyre has nail in tread section & cracked & perished up.
Advice	Offside front cv boot small damage & leakig.

MOT #2	2021-01-22 10:24
MOT test number	860451117795
Result	✗ Failed
Fail	Offside Front Service brake effort inadequate at a wheel (1.2.1 (a) (i))
Advice	Offside rear tyre 3.5mm tread & cracked & perished.
Advice	Front rake disc's lipped & worn.
Advice	Offside front cv boot small damage & leakig.
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside rear tyre has nail in tread section & cracked & perished up.
Advice	Vehicle front under tray damage & loose.
Fail	Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #1	2019-03-22 12:23
MOT test number	101582648377
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
24 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	KN16NSF
Plate since	2019-03-29
Current registration	KN16NSF
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-31
Last registration	2023-08-25
Complete history	See info



Registration #1	2016-03-31	26 mi
Registration #2	2019-03-22	38.399 mi
Registration #3	2021-01-22	45.390 mi
Registration #4	2021-01-25	45.392 mi
Registration #5	2023-08-25	45.392 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		

[More info >](#)



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	1020 kg
Max. allowed weight	1555 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XV120205743