



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX STYLE
Colour	Grey
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	155 Nm at 6.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-27
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #14	2021-12-31 14:29
MOT test number	798101581996
Result	✓ Passed
Next expiry date	2022-12-30
Minor	Front Headlamp lens slightly defective Nearside / Offside (4.1.1 (b) (i))
Advice	General corrosion
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13	2021-03-29 08:17
MOT test number	391522747350
Result	✓ Passed
Advice	Nearside Rear Nail in tyre outer tread

MOT #12	2021-03-29 08:17
MOT test number	560166165545
Result	✗ Failed
Advice	Nearside Rear Nail in tyre outer tread
Pass with rectification	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #11	2019-06-22 08:28
MOT test number	289062600508
Result	✓ Passed
Advice	Advice headlamp beam patterns fading

MOT #10	2018-06-15 15:24
MOT test number	792263162923
Result	✓ Passed

**MOT #9** 2017-06-19 15:19**MOT test number** 566525204971**Result** ✓ Passed**MOT #8** 2016-06-14 14:51**MOT test number** 565224621937**Result** ✓ Passed

- Advice** Nearside front tyre inner edge worn
- Advice** Nearside rear tyre inner edge worn
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside front tyre inner edge worn

MOT #7 2016-06-14 08:45**MOT test number** 847959247038**Result** ✗ Failed

- Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside front tyre inner edge worn
- Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside rear tyre inner edge worn
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside front tyre inner edge worn

**MOT #6** 2015-06-22 14:30**MOT test number** 518683175121**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2014-06-19 12:19**MOT test number** 387710474159**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2013-06-03 09:32**MOT test number** 168094653156**Result** ✓ Passed**Notice** Low washer jet spray**Notice** Baffles rattle in exhaust**MOT #3** 2012-06-11 14:28**MOT test number** 245073062429**Result** ✓ Passed**Notice** Baffles in exhaust rattling



MOT #2	2011-06-13 15:19
MOT test number	288674061471
Result	✓ Passed
Notice	Baffles loose in rear silencer
Notice	Engine management light on

MOT #1	2010-06-23 13:59
MOT test number	490104970136
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-06-30
Last registration	2021-12-31
Complete history	See info



Registration #1	2007-06-30	28 mi
Registration #2	2010-06-23	15.264 mi
Registration #3	2011-06-13	23.884 mi
Registration #4	2012-06-11	31.202 mi
Registration #5	2013-06-03	38.628 mi
Registration #6	2014-06-19	45.670 mi
Registration #7	2015-06-22	52.783 mi
Registration #8	2016-06-14	58.213 mi
Registration #9	2016-06-14	58.213 mi
Registration #10	2016-06-14	58.213 mi
Registration #11	2016-06-14	58.213 mi
Registration #12	2016-06-14	58.213 mi
Registration #13	2016-06-14	58.213 mi
Registration #14	2016-06-14	58.213 mi
Registration #15	2016-06-14	58.213 mi
Registration #16	2016-06-14	58.213 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1344 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

6S61046