





report date: 2024-03-28

#### General information

Make	MINI
Model	MINI COOPER D
Colour	Black
Year of manufacture	2011
Top speed	122 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	А



CarCheck.co.uk page 1/12



Internet history

-		-		1
п	L	ΓV	,	т.

ciitiy 1	
Date	2021-05-22
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



959845158680

MOT history

**MOT test number** 

MOT expiry date	2024-10-05
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #12	2023-09-08 15:05
MOT test number	448833453585
Result	✓ Passed
Next expiry date	2024-10-05
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2022-09-23 15:53
MOT test number	875079970246
Result	<b>✓</b> Passed
MOT #10	2021-10-06 12:52

**Result** ✓ Passed

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #9		2021-01-27 12:01
MOT test	number	505223986398
Result		✓ Passed
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i	))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



**MOT #8** 2020-02-08 10:51

**MOT test number** 441660414411

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #7** 2019-02-09 09:06

**MOT test number** 326939392794

Result \sqrt{Passed}

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2018-02-05 15:26

**MOT test number** 232025258405

Result \( \sqrt{Passed} \)

**Advice** Items removed from driver's view prior to test

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' x 2 (8.3.1d)

MOT #5 2018-02-05 15:07

MOT test number 868959871027

Result × Failed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' x 2 (8.3.1d)

**Advice** Items removed from driver's view prior to test

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

MOT #4 2017-01-11 09:28

**MOT test number** 856798533170

**Result** ✓ Passed

CarCheck.co.uk page 4/12



WF11DZC

report date: 2024-03-28

MOT #3	2016-02-01 10:32
MOT test number	471638973929
Result	✓ Passed
MOT #2	2015-02-02 12:32
MOT test number	925683935068
Result	✓ Passed
MOT #1	2014-03-21 11:50
MOT test number	189540584084
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limi	(4.1.E.1)
Advice Offside Front Tyre worn close to the legal limit (	4.1.E.1)
Notice N/s wiper blade ends split	

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	5 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MINI salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

WF11DZC

report date: 2024-03-28

For how long did the current and previous owner(s) have this MINI? How many owners did this M Check it in the premium report and see all owner registrations. Download the full report <u>here</u> .	INI have?
THE PARTY OF THE P	
THE PROPERTY OF THE PROPERTY O	

More info >

# Plate changes

More info >

CarCheck.co.uk page 9/12



WF11DZC

report date: 2024-03-28

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



WF11DZC

report date: 2024-03-28

### Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-25
Last registration	2023-09-08
Complete history	See info



Registration #1	2011-03-25	8 mi
Registration #2	2014-03-21	23.825 mi
Registration #3	2015-02-02	26.639 mi
Registration #4	2016-02-01	34.099 mi
Registration #5	2017-01-11	43.963 mi
Registration #6	2018-02-05	49.786 mi
Registration #7	2018-02-05	49.786 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

# Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles 2

Engine number 70757967