





report date: 2024-03-29

General information

Make	AUDI
Model	TT S3 QUATTRO
Colour	Blue
Year of manufacture	2002
Top speed	151 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	221 BHP
Max. torque	280 Nm at 2.200 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	21.6 mpg
Consumption combined	39.8 mpg
CO2 emission	226 g/km
CO2 label	L



CarCheck.co.uk page 1/14



report date: 2024-03-29

MOT history

MOT expiry date	2023-01-09
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	39
Total items failed	20

MOT #23		2022 01 10 15.46
MOT test	numbor	2022-01-10 15:46 657820596370
Result	indinaei	✓ Passed
		·
Next expi	ry date	2023-01-09
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Various under body components under sealed	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice corroded (Brake pipe corroded, covered in grease or other material Both rear brake pipe 1.1.11 (c))	pes to caliper flexis

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT #22 2021-12-29 16:26 338302035588 **MOT** test number Result × Failed Fail Rear Brake pipe excessively corroded both (1.1.11 (c)) Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) **Advice** Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b)) Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Front Coil spring corroded both (5.3.1 (b) (i)) Fail Front Position lamp not working both (4.2.1 (a) (ii)) **Advice** Power staring pipe hanging

MOT #21	2021-01-08 10:21
MOT test number	459486153960
Result	. ✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #20 2019-07-05 12:02

MOT test number 793573831736

Result ✓ Passed

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #19 2019-07-04 11:44

MOT test number 771935630443

Result X Failed

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Fail Exhaust emits dense blue smoke at idle (8.2.1.2 (f))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #18	2017-11-18 11:19
MOT test number	168998683761
Result	✓ Passed
Advice Nearside Rear tyre damaged on outer wall	

MOT #17	2017-11-11 14:38
MOT test number	430025555159
Result	X Failed
Advice Nearside Rear tyre damaged on outer wall	
Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)	
Fail Nearside Front Tyre not fitted in accordance w	rith side wall instructions (4.1.D.1f)

MOT #16	2016-11-23 10:23
MOT test number	759024373976
Result	✓ Passed
MOT #15	2016-01-15 17:14
MOT test number	396104655441
Result	✓ Passed
MOT #14	2015-04-04 10:42
MOT test number	828924195031
Result	✓ Passed
MOT #13	2014-03-22 09:23
MOT test number	655141084000
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #12 2013-04-12 09:31 **MOT test number** 728712603170 Result ✓ Passed 2012-04-14 09:55 MOT #11 **MOT** test number 108505402131 Result ✓ Passed **Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c) **Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3) Notice Battery insecure **Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #10		2012-04-14 09:55
MOT test	number	295725002493
Result		X Failed
Advice Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)		
Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)		
Notice Battery insecure		
Pass wit	th rectification Brake pipe inadequately clipped (3.6.B.1)	
Advice Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)		

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #9		2011-04-18 16:10
MOT test	number	727418701140
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #8	2010-04-15 11:26
MOT test number	274975500469
Result	✓ Passed
MOT #7	2010-04-15 10:25
MOT test number	701645100132
Result	X Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #6	2009-03-27 17:32
MOT test number	171066889497
Result	✓ Passed

MOT #5		2009-03-26 16:27
MOT te	st number	634865389066
Result		🗙 Failed
Fail	Front passenger seat insecure (6.2.3)	
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.	3)
Fail	Offside Registration plate lamp not working (1.1.5c)	
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)	

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #	4	2008-04-17 14:16
MOT te	est number	541168308136
Result		✓ Passed
MOT #3	3	2008-04-15 15:48
MOT te	est number	853596408105
Result		★ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)	
Fail	Offside Windscreen wiper blade missing (8.2.2)	
Fail	Registration plate lamp not working (1.1.5c)	

MOT #2	2007-04-10 16:40
MOT test number	111100907121
Result	✓ Passed
MOT #1	2006-04-14 09:54
MOTILATION	201661206115

	2000 04 14 05.54
number	304664306145
	✓ Passed
Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Offside Front Tyre worn close to the legal limit (4.1.E.1)	
	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner	history
OWITE	HISLULY

For how long did the current and previous owner(s) have this AUDI? How many owners did Check it in the premium report and see all owner registrations. Download the full report \underline{h}		ve?
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	UK C	
Plate since		
Current registration	NK NAME OF THE PROPERTY OF THE	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-06-01
Last registration	2022-01-10
Complete history	See info



Registration #1	2002-06-01	9 mi
Registration #2	2006-04-14	10.969 mi
Registration #3	2007-04-10	16.459 mi
Registration #4	2008-04-15	23.002 mi
Registration #5	2008-04-17	23.002 mi
Registration #6	2009-03-26	29.617 mi
Registration #7	2009-03-27	29.617 mi
Registration #8	2010-04-15	44.490 mi
Registration #9	2010-04-15	44.496 mi
Registration #10	2011-04-18	56.767 mi
Registration #11	2012-04-14	64.082 mi
Registration #12	2013-04-12	72.181 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.117 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditioning
60295	
0482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1415 mm
Length	4159 mm
Wheel base	2519 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number CarCheck.co.uk	BAM 037674 page 14/14