






report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI PLUS
Colour	Grey
Year of manufacture	2014
Top speed	102 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP	
Max. torque	215 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	46.3 mpg	
Consumption extra urban	61.4 mpg	
Consumption combined	54.3 mpg	



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 5

Date 2024-02-12

Pictures 0

Listing price View report

source: carcraft.co.uk

Entry 4

Date 2023-12-05

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 3

Date 2023-09-06

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2022-08-20

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1


Date	2021-01-29
Pictures	5

CarCheck.co.uk page 2/11

View report









source: autoonline.co.uk



WA64JKE

report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2023-10-03
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #6	2022-10-04 10:11
MOT test number	548106110918
Result	✓ Passed
Next expiry date	2023-10-03

MOT #5	2021-07-20 16:14
MOT test number	311927691610
Result	✓ Passed

MOT #4	2019-09-04 08:57
MOT test number	443610300524
Result	✓ Passed

MOT #3		2018-10-08 10:29
MOT test	number	951171175995
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Items removed from driver's view prior to test	
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

CarCheck.co.uk page 3/11



MOT #2 2018-10-08 10:29

MOT test number 821433380015

Result × Failed

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Items removed from driver's view prior to test

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Pass with rectification Offside Registration plate lamp inoperative in the case of a single lamp or all

lamps (4.7.1 (b) (ii))

MOT #1 2017-10-11 08:39

MOT test number 396335988529

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Items removed from driver's view prior to test

CarCheck.co.uk page 4/11



Tax & MOT check





Tax status Expired at 23 August 2023

Days left 250 days too late

MOT expiry date 3 October 2023

Full MOT history See MOT history

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



furthe scinors

WA64JKE

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.

ば UK

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-10
Last registration	2022-10-04
Complete history	See info



Registration #1	2014-11-10	24 mi
Registration #2	2017-10-11	14.785 mi
Registration #3	2018-10-08	20.204 mi
Registration #4	2018-10-08	20.204 mi
Registration #5	2019-09-04	24.895 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.117 es
Registration #9		11.777 es
Registration #10		11.117 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Dimensions & weight

Width	1810 mm
Height	1852 mm
Length	4380 mm
Wheel base	2728 mm
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	JBEM3089831

CarCheck.co.uk page 11/11