



HONDA



YH60NXV

report date: 2024-03-28

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	White
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-08-25
Pictures	28
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-24
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #12	2023-10-25 13:01
MOT test number	813691434450
Result	✓ Passed
Next expiry date	2024-10-24
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-10-24 12:32
MOT test number	616082768666
Result	✓ Passed

MOT #10	2021-09-24 13:33
MOT test number	676959696131
Result	✓ Passed
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9** 2021-09-22 10:57**MOT test number** 550534629669**Result** ✗ Failed

MAJOR Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #8 2020-09-25 14:35**MOT test number** 689121143319**Result** ✓ Passed**MOT #7** 2019-06-07 12:13**MOT test number** 937505551868**Result** ✓ Passed**MOT #6** 2018-06-08 07:59**MOT test number** 501304766435**Result** ✓ Passed

Advice Front Tyre has a cut but not deep enough to reach the ply or cords cracking between treads 195/55/16v (both) (5.2.3 (d) (i))

Advice Rear Tyre has a cut but not deep enough to reach the ply or cords cracking between treads 195/55/16v (both) (5.2.3 (d) (i))

MOT #5 2017-06-08 08:52**MOT test number** 310788373978**Result** ✓ Passed



MOT #4	2016-06-10 10:07
MOT test number	758872364558
Result	✓ Passed
MOT #3	2015-05-18 16:42
MOT test number	518758035154
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Items removed from driver's view prior to test
MOT #2	2014-06-07 08:47
MOT test number	828428654197
Result	✓ Passed
MOT #1	2013-10-21 13:00
MOT test number	808414793228
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-10-27
Last registration	2023-10-25
Complete history	See info



Registration #1	2010-10-27	6 mi
Registration #2	2013-10-21	11.417 mi
Registration #3	2014-06-07	13.687 mi
Registration #4	2015-05-18	25.734 mi
Registration #5	2016-06-10	44.053 mi
Registration #6	2017-06-08	50.700 mi
Registration #7	2018-06-08	55.984 mi
Registration #8	2019-06-08	55.984 mi
Registration #9	2019-06-08	55.984 mi
Registration #10	2019-06-08	55.984 mi
Registration #11	2019-06-08	55.984 mi
Registration #12	2019-06-08	55.984 mi
Registration #13	2019-06-08	55.984 mi
Registration #14	2019-06-08	55.984 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1016382