





report date: 2024-03-29

General information

| Make | RENAULT |
|---------------------|-----------------|
| Model | TWINGO PLAY SCE |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 94 mph |
| 0 - 60 mph | 14.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 70 BHP |
|-------------------------|--------------------|
| Max. torque | 91 Nm at 2.850 rpm |
| Engine capacity | 999 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 60.1 mpg |
| CO2 emission | 105 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



Internet history

| E ~ | + | , 1 |
|-----|-------|-----|
| | ILI V | , . |

| Life y 1 | |
|---------------|-------------|
| Date | 2021-10-17 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-10-19 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 13 |
| Total items failed | 0 |

| MOT #6 | 2023-10-18 13:47 |
|--|----------------------------|
| MOT test number | 634302940227 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-19 |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weak disc (1.1.14 (a) (ii)) | kened disc pitted & lip on |
| Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice Nearside Front lip on disc | |
| Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movements anti-roll bar bushes cracking no play in bushes (5.3.4 (a) (i)) | rement advise both front |

| MOT #5 | 2022-10-06 14:48 |
|-----------------|------------------|
| MOT test number | 315478952783 |
| Result | ✓ Passed |

| MOT #4 | | 2021-10-13 09:24 |
|----------|---|------------------|
| MOT test | number | 699117743773 |
| Result | | ✓ Passed |
| Advice | Undertrays, sill covers & trims within prescribed area not allowing full inspection | ı |

CarCheck.co.uk page 3/11



MOT #3 2020-10-20 12:22

MOT test number 706390927304

Result ✓ Passed

Advice

Undertrays & trims within prescribed area not allowing full inspection

MOT #2 2019-04-11 14:09

MOT test number 257410146734

Result

Passed

Advice Offside Rear tyre slightly wearing outer edge

MOT #1 2019-04-10 14:06

MOT test number 942771254474

Result X Failed

Advice Offside Rear tyre slightly wearing outer edge

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm wearing edges close to canvas (5.2.3 (e))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm wearing inner edge close to canvas (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing inner and outer edges and perishing (5.2.3 (e))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 154 |
| MOT expiry date | 19 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| e union matery | |
|---|-------------|
| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
| | |
| | |
| *************************************** | |
| | |
| | |
| | |
| | |
| | More info > |
| Plate changes See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Flate since | |
| Current registration | UK NEZ |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0.1.116 | |

Contact info

More info >

CarCheck.co.uk page 9/11



CU16YRE

report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-03-25 |
| Last registration | 2023-10-18 |
| Complete history | See info |



| Registration #1 | 2016-03-25 | 28 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-04-10 | 41.182 mi |
| Registration #3 | 2019-04-11 | 41.182 mi |
| Registration #4 | 2020-10-20 | 42.016 mi |
| Registration #5 | | 9.70 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 78% |
| Children | 81% |
| Pedestrian | 68% |
| Safety systems | 56% |
| Overall rating | 72% |
| Video | see crash video |



Dimensions & weight

| Width | 1646 mm |
|---------------------|---------|
| Height | 1554 mm |
| Length | 3595 mm |
| Wheel base | 2492 mm |
| Kerb weight | 864 kg |
| Max. allowed weight | 1359 kg |

Additional information

| Fuel tank capacity | 35 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 4 page 11/11 |

Number of axles 2

Engine number U216626