





report date: 2024-03-28

General information

Make	TOYOTA
Model	AURIS VVT-I EXCEL
Colour	White
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	98 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	72.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	72.4 mpg
CO2 emission	91 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2023-04-05

Pictures 41

Listing price View report









source: cargurus.co.uk

Entry 1

Date	2021-06-15
Pictures	8

Listing price View report









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-27
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #12	2024-02-29 10:28
MOT test number	432694703697
Result	✓ Passed
Next expiry date	2025-03-27
Advice Tested under wet conditions	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	ī

MOT #11	2023-03-28 10:59
MOT test number	740233131752
Result	✓ Passed

MOT #10	2	2021-11-13 10:45
MOT test	number	261667028794
Result		✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive move	ement (5.3.4 (a)
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive mo	vement (5.3.4

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

484831793801

Result

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #8 2020-10-23 11:08 **MOT** test number 390368435823 Result × Failed Fail Offside Front Headlamp not working on main beam (4.1.1 (a) (ii)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i)) Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #7		2019-11-01 15:04
MOT test	number	943772786838
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively Both sides (1.1.14 (a) (i))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Engine covers & Under shield fitted obscuring some components	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6 2018-11-09 16:56

MOT test number 375806406719

Result
✓ Passed

MOT #5 2017-11-16 12:06

MOT test number 896573860967

Result ✓ Passed

MOT #4 2017-11-13 13:22

MOT test number 381488916688

Result X Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 225/45/17 91W (4.1.D.1a)

MOT #3 2016-11-03 09:58

MOT test number 174039387161

Result ✓ Passed

MOT #2 2016-11-03 09:58

MOT test number 720770107692

Result X Failed

Pass with rectification Offside Front Headlamp not working on dipped beam (1.7.5a)

MOT #1 2015-11-06 10:39

MOT test number 783750643920

Result \rightarrow Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report here .		
manage of the same		

	More info >	
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates	,	
Current registration	NK NK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-09
Last registration	2024-02-29
Complete history	See info



Registration #1	2012-11-09	11 mi
Registration #2	2015-11-06	28.491 mi
Registration #3	2016-11-03	44.068 mi
Registration #4	2016-11-03	44.068 mi
Registration #5	2017-11-13	56.084 mi
Registration #6	2017-11-16	56.084 mi
Registration #7	2018-11-09	64.666 mi
Registration #8	2019-11-01	73.713 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1475 mm
Length	4330 mm
Wheel base	2600 mm
Kerb weight	1420 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Engine number

2ZRU572498