





report date: 2024-03-29

General information

Make	MINI
Model	COOPER S AUTO COOPER S
Colour	Red
Year of manufacture	2011
Top speed	139 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date	2021-10-11
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-05
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #13		2023-10-04 10:17
MOT test	number	739709565573
Result		✓ Passed
Next expi	ry date	2024-10-05
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Undertrays fitted	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Both rear tyres slightly out of shape	

MOT #12	2022-10-01 10:08
MOT test number	366525161881
Result	✓ Passed
MOT #11	2021-10-06 07:14

MOT #11	2021-10-06 07:14
MOT test number	265281697145
Result	✓ Passed

MOT #10	2020-11-24 16:39
MOT test number	987715565236
Result	✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Inner faces in poor condition - On limit (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



GU11XFT

report date: 2024-03-29

MOT #9 2019-11-25 14:50

MOT test number 481110898477

Result \rightarrow Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2019-11-20 10:39

MOT test number 820293630700

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #7 2018-11-23 15:26

MOT test number 970070902415

Result ✓ Passed

MOT #6 2017-11-18 10:21

MOT test number 132902519347

Result ✓ Passed

MOT #5 2017-04-10 07:54

MOT test number 123740802216

Result \(\sqrt{Passed} \)

Advice Central Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4 2016-03-30 08:12

MOT test number 502208169874

Result
✓ Passed

CarCheck.co.uk page 4/12



GU11XFT

report date: 2024-03-29

MOT #3		2015-04-02 17:04
MOT test	number	216462395033
Result		✓ Passed
MOT #2		2014-03-08 09:28
MOT test	number	115497264485
Result		✓ Passed
Notice	Nearside front tyre tread low on outer edge.	
Notice	Under-trays fitted obscuring some underside components	
Notice	Offside front tyre tread low on outer edge.	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #1		2014-03-08 09:28
MOT test	number	416347864018
Result		🗙 Failed
Notice	Nearside front tyre tread low on outer edge.	
Notice	Under-trays fitted obscuring some underside components	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Offside front tyre tread low on outer edge.		
Notice Engine covers fitted obscuring some components in the engine bay		
Pass wit	h rectification Nearside Registration plate lamp not working (1.1.C.1d)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner mistory	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
	More into >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-26
Last registration	2023-10-04
Complete history	See info



Registration #1	2011-03-26	16 mi
Registration #2	2014-03-08	12.128 mi
Registration #3	2015-04-02	14.492 mi
Registration #4	2016-03-30	17.012 mi
Registration #5	2017-04-10	18.722 mi
Registration #6	2017-11-18	19.421 mi
Registration #7	2018-11-23	21.371 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		91.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1155 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles2Engine numberB787J085